

50-331

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
ENVIRO

TO:
Mr. Edson G. Case

FROM:
IOWA ELEC. LIGHT & PWR. CO.
Cedar Rapids, Iowa
Ellery L. Hammond

DATE OF DOCUMENT
11/29/77

DATE RECEIVED
12/9/77

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
100

DESCRIPTION

Licensee Event Report (Environ. 77-07) on 11/20/77 concerning liquid and airborne effluent radiation monitor sensor checks being inadvertently not performed.....

PLANT NAME : Duane Arnold
RJL 12/9/77 (2-P)

ENCLOSURE

SAFETY	FOR ACTION/INFORMATION	ENVIRONMENTAL
ASSIGNED AD:		ASSIGNED AD: V. MOORE (LTR)
BRANCH CHIEF: (7)	LEAR	BRANCH CHIEF:
PROJECT MANAGER:		PROJECT MANAGER:
LIC. ASST:		LIC. ASST:
		B. HARLESS

INTERNAL DISTRIBUTION			
REG FILES	SYSTEMS SAFETY	PLANT SYSTEMS	SITE SAFETY & ENVIRON ANALYSIS
NRC PDR	R. MATTSO	TEDESCO	DENTON & MULLER
I & E (12)	SCHROEDER	BENAROYA	GRUTCHFIELD
OELD		LAINAS	
GOSSICK & STAFF	ENGINEERING	IPPOLITO	
HANAUER	KNIGHT	F. ROSA	ENVIRON TECH
MIPC	BOSNAK		ERNST
CASE	SIHWEIL	OPERATING REACTORS	BALLARD
BOYD	PAWLICKI	STELLO	YOUNGBLOOD
		EISENHUT	
PROJECT MANAGEMENT	REACTOR SAFETY	SHAO	SITE TECH
SKOVHOLT	ROSS	BAER	GAMMILL (2)
P. COLLINS	NOVAK	BUTLER	
HOUSTON	ROSZTOCZY	GRIMES	SITE ANALYSIS
MELTZ	CHECK	L. CROCKER	VOLLMER
HELTEMES			BUNCH
SK	AT & I		J. COLLINS
	SALTZMAN		KREGER
	RUTBERG		


EXTERNAL DISTRIBUTION			CONTROL NUMBER
LPDR: CEDAR RAPIDS	NAT LAB: ANL		773430030 Env. 1 60
TIC			
NSIC			
REG V (J. HANCHETT)			
1 COPY SENT CATEGORY B TO ACRS			

D. Lanham

REGULATORY DOCKET FILE COPY

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
November 29, 1977
DAEC-77-587



Mr. Edson G. Case, Acting Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
1717 H. Street N.W.
Washington, D.C. 20545

Re: Duane Arnold Energy Center
Subject: Environmental Technical Specification
Violation Report 77-07
File: A-117

Dear Mr. Case:

This report is submitted in accordance with the requirements of Appendix B to Operating License DPR-49, Specification 5.4.2.1.

Problem

On November 20, 1977, liquid and airborne effluent radiation monitor sensor checks were inadvertently not performed.

Investigation

Sensor checks are normally performed by Chemistry Department Personnel on weekdays and by the Radwaste Operators on weekends. Due to an oversight, the on-duty Radwaste Operators failed to perform sensor checks on the above date. No abnormalities were identified when the sensor checks were performed the next day.

Corrective Action

Plant personnel involved will be instructed on the requirements for performing daily sensor checks. In addition, a step has been added to the Operations Daily Shift Instrument Checks requiring verification that sensor checks have been performed.

DEC 5 1977

773430030

Mr: Edson G. Case
Page 2
November 29, 1977

This report has been reviewed and approved by the DAEC Operations Committee and Safety Committee.

Very truly yours,

Ellery L. Hammond

Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

ELH/DLW/nf

cc: ~~Mr.~~ J. Keppler

RECEIVED DOCUMENT
SING UNIT

977 DEC 8 PM 12 00