

Appendix ANOTICE OF VIOLATION

Iowa Electric Light and Power Company

Docket No. 50-331

Based on the inspection conducted on March 18-21, 1980, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. These items are infractions.

1. Technical Specification section 6.8.2 states in part: "Procedures ...and changes thereto, shall be reviewed...and approved...prior to implementation except as noted in section 6.8.3..." Technical Specification section 6.8.3 states in part: "Temporary minor changes to procedures...which do not change the intent...may be made with the concurrence of two members of the plant management..."

Contrary to the above, between March 10 and March 18, 1980, numerous changes to procedure RP83/ie-2 Revision 1 were made without either prior approval or concurrence by two members of the plant management.

2. 10 CFR 50 Appendix B Criteria XVI "Corrective Action" states in part..."Measures shall be established to assure that conditions adverse to quality...are promptly identified and corrected..." Iowa Electric Quality Directive 1316.1 "Corrective Action" states: "Systems shall be implemented to assure that conditions adverse to quality are promptly identified and corrected as soon as possible."

Contrary to the above, between March 10 and March 18, 1980 numerous items were identified, during QC inspections dealing with failure to follow procedure RP83/ie-2 revision 1, with no prompt corrective action being taken to correct the situation.