

UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

MAY 3 0 1980

Docket No. 50-331

Iowa Electric Light and Power
Company
ATTN: Mr. Duane Arnold
President
IE Towers
P. O. Box 351
Cedar Rapids, IA 52406

Gentlemen:

Thank you for your letter dated April 30, 1980, informing us of the steps you have taken to correct the noncompliance identified in our letter dated April 8, 1980.

Your letter takes issue with some aspects of the two items of noncompliance identified in our inspection report. As Mr. Geoffrey Wright has discussed with you, we believe the items are valid and address your statements in the following paragraphs.

INFRACTION NO. 1

Iowa Electric onsite management and the NRC inspector agreed that the intent of DCF 2439, as stated in Report 50-331/80-04, was to allow the deletion of procedural steps, if in the vendor representatives opinion, a specific portion of the valve did not require maintenance. The changes which were made to the procedure fell outside of the DCF's authority and should have been reviewed and approved. Therefore, it is our position that failure to implement the requirements of Technical Specification section 6.8.2 remains an item of noncompliance at the infraction level.

INFRACTION NO. 2

It is our position that the item's documented in the General Inspection Reports constitute violation of procedure RP 83/ie-2 and corrective action should have been taken. As no action was taken, the requirements of 10 CFR 50 Appendix B, Criteria XVI were not adhered to and this remains an item of noncompliance at the infraction level.



Your cooperation with us is appreciated.

Sincerely,

R. F. Heishman, Chief Reactor Operations and Nuclear Support Branch

ec: Mr. D. Mineck, Chief Engineer

cc w/ltr dtd 4/30/80: Central Files Reproduction Unit NRC 20b PDR Local PDR NSIC TIC

OFFICE.	RIII	RIII Little	Heisman	P Noose	145	Stole	
	Wright/r1 5/27/80	TITE (Heish an	5/28	180	5/28/80	