

Appendix

NOTICE OF VIOLATION

Iowa Electric Light and
Power Company

Docket No. 50-331

As a result of the inspection conducted on October 1-30, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified:

Technical Specification 3.7.E states "Reactor operation is permissible during the succeeding thirty days after one MSIV-LCS subsystem is made or found to be inoperable provided the other subsystems are operable. If the requirements of 3.7.E cannot be met the reactor shall be in cold shutdown within 24 hours."

Contrary to the above, the "D" MSIV-LCS subsystem was made inoperable during the refueling outage ending June 1, 1981, and the reactor was operated in excess of 30 days prior to discovery of the inoperable subsystem on October 17, 1981.

This is a Severity Level IV violation (Supplement I).

The inspection showed that action was being taken to correct the identified item of noncompliance and to prevent recurrence. Consequently, no reply to this item of noncompliance is required. We will review this action during future inspections.

DEC 11 1981

"Original signed by R.L. Spessard"

Dated _____

R. L. Spessard, Director
Division of Resident and
Project Inspection

8112240197 811221
PDR ADOCK 05000331
Q PDR