

NRC Medium Voltage Circuit Breaker Training



Attachment 8A

ABB HK Work Shop

Remove front cover




Racking Mechanism gap check




Checking puffer operation




Checking the gap on the control device actuator




Trapping the springs for slow close




Slow closing to check simultaneous meet



Main contact pressure check



INSPECT the groove pins



Remove and lubricate MOC Switch Actuator

