Central

Iowa Electric Light and Power Company

November 10, 1980 LDR-80-335

LARRY D. ROOT
ASSISTANT VICE PRESIDENT
NUCLEAR GENERATION

US NAC DISTRIBUTION SERVICES SERVICES UNIT

Mr. James G. Keppler, Director Office of Inspection and Enforcement Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

This letter and attachment contain our final response to IE Bulletin No. 80-11 concerning masonry wall design. This material supercedes our previous submittal regarding this bulletin.

Our review of block walls at the Duane Arnold Energy Center did reveal possible localized overstressing of three block walls during a seismic event and one block wall under a postulated pipe break. For these cases a review of location and function of safety-related systems and components in the light of the possible failure has shown that a failure will have no effect on the operation of any safety-related system or component.

In accordance with a schedule extension which was allowed by Mr. E. Gallagher of your office on November 3, 1980, you will find that we have made this submittal approximately one week later than the response interval given in the bulletin.

NOV: 1 2 1980]

Drawing available in RIII administrative Files (#6820) - too large to reproduce.

8011280028



The information in the foregoing letter and attachment is true and accurate to the best of my knowledge and belief.

IOWA ELECTRIC LIGHT AND POWER COMPANY

Larry D. Root Assistant Vice President Nuclear Generation

Subscribed to and Sworn to Before Me on this 10th day of November 19 80

State of Iowa

MARY E. BENFIELD

COMMISSION EXPIRING SEPTEMBER 30, 1983

LDR/RFS/1d Enclosure

cc: w/o

R. Salmon

- D. Arnold
- L. Liu S. Tuthill
- K. Meyer
- D. Mineck
- J. Van Sickel
- K. Eccleston (NRC)

w/ NRC Resident Office File: A-101a, BN80-11

U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Division of Reactor Operations Inspection Washington, D.C. 20555