## REGULATRY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8104230591 DOC.DATE: 81/04/20 NOTARIZED: NO DOCKET:#
FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
AUTH\_NAME: AUTHOR AFFILIATION

AUTH.NAME: AUTHO RAGER,M.S. Iowa E

Iowa Electric Light & Power Co.

RECIP. NAME

RECIPIENT AFFILIATION

Region 3, Chicago, Office of the Director

SUBJECT: Updated LER 81=010/03X=1:on 810224, during testing, fan for standby filter: Unit B found inoperative. Caused by personnel inadvertently opening Unit B fan breaker instead of Unit A fan breaker. Personnel reinstructed.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR L ENCL L SIZE: 1+2
TITLE: Incident: Reports

NOTES:

| ACTION:   | RECIPIENT ID CODE/NAME IPPOLITO,T.                          |  | OPIES<br>TTR 6   |   | RECIPIEN<br>ID CODE/N  |  | COP1   | ES ENCL  |
|-----------|---|--|--|---|--|--|--|--|
|           | LIC GUID BR<br>MECH ENG BR<br>OR ASSESS BR<br>RAD ASSESS BR | 16<br>18<br>21<br>26<br>30<br>33<br>35<br>39 | 1<br>1<br>1<br>3<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1 | 1<br>1<br>1<br>1<br>3<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1 | A/D ENV TE<br>A/D OP REA<br>A/D RAD PR<br>ACC EVAL B<br>AEOD/DMU<br>AUX SYS BR<br>CONT SYS B<br>DIR, ENGINE<br>DIR, SYS IN<br>EQUIP QUAL<br>1&C SYS BR<br>JORDAN, E./<br>MATL ENG B<br>NRC PDR<br>POWER SYS<br>REACT SYS<br>REL & RISK<br>STRUCT ENG | CTO09<br>OT 11<br>R 14<br>15<br>R 17<br>ERIZO<br>TEG22<br>BR25<br>29<br>IE<br>R 32<br>BR 36<br>BR 40<br>A 41 | 1<br>1<br>1<br>3<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1 | 1<br>1<br>1<br>3<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1<br>1 |
| EXTERNAL: | ***   | 46°<br>05:                                   | 16   | 16<br>1   | LPDR:  | 03   | 1  | 1  |

APR 2 7 1981

20/1



U.S. NUCLEAR REGULATORY COMMISSION DATE REPORT: Previous Report Date 3-25-81

|           | CONTROL BLOCK: [ ] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)   |
|-----------|---|
| 0 1       | 1 A 0 A C 1 2 0 0 - 0 0 0 0 - 0 0 0 4 1 1 1 1 4 57 CAT 58   |
| CON'T     | SOURCE 50 61 DOCKET NUMBER 50 69 EVENT DATE 74 75 REPORT DATE 30  |
| 0 2       | EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)  [ During surveillance testing of the Standb/ Filter Units (SBFU), the fan f   |
| 0 3       | or SBFU "B" was found not running during an operational test. Investigati   |
| 0 4       | on revealed the breaker for the Control Bldg Emerg Air Supply Fan, 1V-SF-   |
| 0 5       | 30B, had been opened by Operations personnel. Tech Spec 3.10.A.3 requires   |
| 0 6       | both trains of the SBFU to be operable during reactor operation. The "A"  |
| 0 7       | SBFU had previously been operationally tested sat and was available for a   |
| 08        | uto initiation. No previous occurrences of this nature have been recorded.  9  SYSTEM CAUSE CAUSE  COMP. VALVE  |
| 0 9       | CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE  S   G  |
| er -      | LER/RO EVENT YEAR REPORT NO.  17 REPORT NO.  18 1 22 23 24 26 27 28 29 30 30 31 32 31 32 32 32 34 32 31 32 32 32 34 32 30 31 32 32 32 34 32 31 32 32 32 32 32 32 32 32 32 32 32 32 32 |
| 10        | Personnel error. Preventative maintenance on "A" SBFU required its break  |
|           | Ler be opened. Ops personnel inadvertently opened the "B" SBFU fan breake   |
| 1 2       | r instead. This interrupted operational run of "B" SBFU and caused B-tra  |
| 13        | in to be inop. Brkr open for approx 10.5 hrs. Operational test completed  |
| ांग       | sat. Ops personnel reinstructed. Plant procedures will be reviewed.   |
| 15        | FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32    E   28   0   9   5   29   NA   B   31   Surveillance Testing   80   |
|           | CTIVITY CONTENT  ELEASED OF RELEASE  AMOUNT OF ACTIVITY 35  LOCATION OF RELEASE 36  NA  NA  NA  NA  NA  NA  NA  NA  NA  N   |
| 17        | PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39  O O O O O NA  NA  NA  NA  |
| 13        | PERSONNEL INJURIES NUMBER DESCRIPTION 41  O O O O O NA  NA  S 11 12   |
| जि        | LOSS OF DR DAMAGE TO FACILITY 43 TYPE DESCRIPTION    Z (42)  NA   |
| 7 8       | PUBLICITY ISSUED DESCRIPTION 45 NAC USE ONLY  |
| 20<br>810 | N(44) NA SE 69 80.  |
| 9.        | NAME OF PREPARER Matthew S. Rager PHONE: 319-851-5611   |