

REGULATOR INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8105120322 DOC. DATE: 81/04/21 NOTARIZED: NO DOCKET #  
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331  
 AUTH. NAME: AUTHOR AFFILIATION  
 MINECK, D.L. Iowa Electric Light & Power Co.  
 RECIP. NAME: RECIPIENT AFFILIATION  
 KEPPLER, J.G. Division of Emergency Preparedness & Operational Support

SUBJECT: RO: during annual surveillance insp on standby diesel generator 1G-21, lower crankshaft bearing 4 was found to have flashing on horizontal surface. Cause not stated. Bearing will be replaced.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2  
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
	IPPOLITO, T. 04	3				
INTERNAL:	A/D COMP&STRU06	1		A/D ENV TECH 07	1	
	A/D MATL & QU08	1		A/D OP REACT009	1	
	A/D PLANT SYS10	1		A/D RAD PROT 11	1	
	A/D SFTY ASSE12	1		ACC EVAL BR 14	1	
	AEOD	3		AEOD/DMU	3	
	ASLBP/J.HARD	1		AUX SYS BR 15	1	
	CHEM ENG BR 16	1		CONT SYS BR 17	1	
	CORE PERF BR 18	1		DIR, ENGINEER120	1	
	DIR, HUM FAC S21	1		DIR, SYS INTEG22	1	
	EFF TR SYS BR23	1		EQUIP QUAL BR25	1	
	GEOSCIENCES 26	1		I&C SYS BR 29	1	
	I&E 05	1		JORDAN, E./IE	1	
	LIC GUID BR 30	1		MATL ENG BR 32	1	
	MECH ENG BR 33	1		NRC PDR 02	1	
	OR ASSESS BR 35	1		POWER SYS BR 36	1	
	RAD ASSESS BR39	1		REACT SYS BR 40	1	
	<b>REG FILE</b> 01	1		REL & RISK A 41	1	
	SFTY PROG. EVA42	1		STRUCT ENG BR44	1	
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	
	NSIC 05	1				

MAY 13 1981

PO/I  
4

*[Handwritten signature]*

TOTAL NUMBER OF COPIES REQUIRED: LTR 61 ENCL 1

Iowa Electric Light and Power Company

April 21, 1981  
DAEC-81-252



Mr. James G. Keppler, Director  
Office of Inspection and Enforcement - Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Subject: Prompt Notification of a  
Reportable Occurrence

File: A-118a

Dear Mr. Keppler:

This letter, telecopied to your office, is intended to satisfy the requirement for prompt notification of a Reportable Occurrence in accordance with Specification 6.11.2.a of the Duane Arnold Energy Center Technical Specifications.

Technical Specification Paragraph(s) violated: None

Description Occurrence: During an annual surveillance inspection conducted on standby diesel generator 1G-21, the lower crankshaft bearing #14 was found to have flashing on the horizontal (journal) surface. This bearing will be replaced. Vendor inspection work and investigation of the standby diesel generator 1G-21 bearing problem is continuing.

Very truly yours,

Daniel L. Mineck  
Chief Engineer  
Duane Arnold Energy Center

DLM/DWT/p1

cc: Director Management Information and Program Control (2)  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

U. S. Nuclear Regulatory Commission  
c/o Document Management Branch  
Washington, D. C. 20555

NRC Resident Inspector

*Handwritten:* Aoor  
5/10

5  
81 05 120322

APR 27 1981

Handwritten scribble or signature in the top left corner.

