

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9012180215      DOC. DATE: 90/12/10      NOTARIZED: NO      DOCKET #  
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow      05000331  
 AUTH. NAME      AUTHOR AFFILIATION  
 MINECK, D.L.      Iowa Electric Light & Power Co.  
 RECIP. NAME      RECIPIENT AFFILIATION  
 MURLEY, T.E.      Office of Nuclear Reactor Regulation, Director (Post 870411 R

SUBJECT: Forwards "Inservice Insp Rept, 881228-900910," per      I  
 NUREG-0313 & NUREG-0619.

DISTRIBUTION CODE: A047D      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 19+245      D  
 TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code      S

NOTES: *see Reports*

	RECIPIENT		COPIES		RECIPIENT		COPIES		
	ID	CODE/NAME	LTR	ENCL	ID	CODE/NAME	LTR	ENCL	
	PD3-3	LA	1	0	PD3-3	PD	1	1	A
	HALL,	J.R.	2	2					D
INTERNAL:	ACRS		6	6	AEOD/DSP/TPAB		1	1	D
	NRR/DET/ECMB	9H	1	1	NRR/DET/EMEB	7E	1	1	S
	NUDOCS-ABSTRACT		1	1	OC/LEMB		1	0	
	OGC/HDS2		1	0	REG FILE	01	1	1	
	RES/DSIR/EIB		1	1					
EXTERNAL:	EG&G BROWN, B		1	1	EG&G RANSOME, C		1	1	
	NRC PDR		1	1	NSIC		1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,  
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION  
 LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 22 ENCL 19

R  
I  
D  
S  
/  
A  
D  
D  
S

Iowa Electric Light and Power Company

December 10, 1990  
NG-90-2858

Dr. Thomas E. Murley, Director  
Office of Nuclear Reactor Regulation  
U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Stop P1-137  
Washington, DC 20555

Subject: Duane Arnold Energy Center  
Docket No: 50-331

Op. License No: DPR-49  
DAEC Inservice Inspection Report

References:

- 1) NUREG-0313, Revision 2, "Technical Report on Material Selection and Processing Guidelines for BWR Coolant Pressure Boundary Piping," January 1988
- 2) NUREG-0619, "BWR Feedwater Nozzle and Control Rod Drive Return Line Nozzle Cracking," November 1980

File: A-107a, A-286a, B-31c, SpF-118

Dear Dr. Murley:

In accordance with the requirements of Paragraph IWA-6230 in Section XI of the ASME Boiler and Pressure Vessel Code and 10 CFR Part 50.55a(g), we herewith submit our 1990 Refueling Outage Inservice Inspection Summary Report. This report addresses examinations which were performed at the Duane Arnold Energy Center (DAEC) during the time period from December 28, 1988 (1988 Refueling Outage Startup) through September 10, 1990 (1990 Refueling Outage Startup).

Attachment 2 provides information regarding augmented inservice inspections performed during the 1990 Refueling Outage in accordance with References 1 and 2.


Our review of the inspection reports has determined that all examined items are acceptable. These inspection reports are on file and are available for your review upon request.

9012180215 901210  
PDR ADOCK 05000331  
Q PDR

Dr. Thomas E. Murley  
December 10, 1990  
NG-90-2858  
Page 2

Should you have any questions regarding the attached information,  
please contact this office.

Very truly yours,



Daniel L. Mineck  
Manager, Nuclear Division

DLM/CJR/pjv\*

Attachments: 1) Inservice Inspection Report (December 28, 1988  
through September 10, 1990)  
2) Augmented Inspection Report for DAEC 1990  
Refueling Outage

cc: C. Rushworth  
L. Liu  
L. Root  
R. McGaughy  
S. Sands (NRC-NRR)  
A. Bert Davis (Region III)  
S. Presler (ANII) (w/o)  
NRC Resident Office (w/o)  
Commitment Control No. 890126