

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9208040087 . DOC. DATE: 92/07/24 NOTARIZED: NO DOCKET #
FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
AUTH. NAME AUTHOR AFFILIATION
FRANZ, J.F. Iowa Electric Light & Power Co.
RECIP. NAME RECIPIENT AFFILIATION
MURLEY, T.E. Document Control Branch (Document Control Desk)

SUBJECT: Forwards "Duane Arnold Energy Center Unit 1 Palo, Iowa
Inservice Insp Summary Rept for 900911 through 920427."

See Report

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+130
TITLE: OR Submittal: Inservice Inspection/Testing/Relief from ASME Code

NOTES:

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL	ID CODE/NAME	LTTR	ENCL	
	PD3-3 LA		1	0	PD3-3 PD	1	1	
	SHIRAKI, C.		2	2				
INTERNAL:	ACRS		6	6	NRR/DET/ECMB 9H	1	1	
	NRR/DET/EMEB 7E		1	1	NUDOCS-ABSTRACT	1	1	
	OC/LEMB		1	0	OGC/HDS2	1	0	
	<u>REG FILE</u> 01		1	1	RES MILLMAN, G	1	1	
	RES/DSIR/EIB		1	1				
EXTERNAL:	EG&G BROWN, B		1	1	EG&G RANSOME, C	1	1	
	NRC PDR		1	1	NSIC	1	1	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 19

*MA-2
dhp*

R
I
D
S
/
A
D
D
S

Iowa Electric Light and Power Company

July 24, 1992
NG-92-3268

JOHN F. FRANZ, JR.
VICE PRESIDENT, NUCLEAR
Dr. Thomas E. Murley, Director
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

Subject: Duane Arnold Energy Center
Docket No: 50-331
Op. License No: DPR-49
DAEC Inservice Inspection Report

Reference: 1) NUREG-0313, Revision 2, "Technical
Report on Material Selection and
Processing Guidelines for BWR
Coolant Pressure Boundary Piping,"
January 1988

2) NUREG-0619, "BWR Feedwater Nozzle
and Control Rod Drive Return Line
Nozzle Cracking," November 1980

3) ASME Section XI "Rules for
Inservice Inspection of Nuclear
Power Plant Components", 1980
Edition including Winter 1981
Addenda

File: A-107a, A-286a, B-31c, SpF-118

Dear Dr. Murley:

In accordance with the requirements of Paragraph IWA-6230 in Section XI of the ASME Boiler and Pressure Vessel Code and 10 CFR Section 50.55a(g), we herewith submit our 1992 Refueling Outage Inservice Inspection Summary Report. This report addresses examinations which were performed at the Duane Arnold Energy Center (DAEC) during the time period from September 11, 1990 (1990 Refueling Outage Startup) through April 27, 1992 (1992 Refueling Outage Startup).

Attachment 2 provides information regarding augmented inservice inspections performed during the 1992 Refueling Outage including those required by References 1 and 2.

Our review of the inspection reports has determined that all examined items are acceptable. These inspection reports are on file and are available for your review upon request.

9208040087 920724
PDR ADDCK 05000331
Q PDR

AD47

Dr. Thomas E. Murley
July 24, 1992
NG-92-3268
Page 2

Should you have any questions regarding the attached information,
please contact this office.

Very truly yours,



John F. Franz, Jr.
Vice President, Nuclear

JFF/SRC/pjv~

Attachments: 1) Inservice Inspection Report (September 11,
1990 through April 27, 1992)
2) Augmented Inspection Report for DAEC 1992
Refueling Outage

cc: S. Catron
L. Liu
L. Root
R. McGaughy
C. Shiraki (NRC-NRR)
A. Bert Davis (Region III)
NRC Resident Office
Commitment Control No. 920089
DCRC
W. Mueller (ANII) (w/o)