



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION IV  
612 EAST LAMAR BLVD, SUITE 400  
ARLINGTON, TEXAS 76011-4125

August 31, 2011

MEMORANDUM TO: Duane White, Health Physicist (MS-8F5)  
Radioactive Materials Safety Branch  
Division of Materials Safety & State Agreements

FROM: Michael Vasquez, Chief */RA/*  
Nuclear Materials Safety Branch A  
Division of Nuclear Materials Safety

SUBJECT: MATERIALS LICENSEE EVENT REPORT SUMMARY

Enclosed is the subject report for August, 2011. This enclosure documents the licensee event reports that were closed the preceding month(s), and lists ADAMS ML numbers for documents associated with these events, detailing Region IV's response to these events.

Enclosure:

August, 2011 RIV DNMS Licensee  
Event Reports Summary Table

cc via email w/Enclosure 1:

- E. Collins
- A. Howell
- R. Caniano
- C. Cain
- V. Campbell
- J. Whitten
- D. Spitzberg
- J. Thompson
- D. Huntsman [Dante.Huntsman@inl.gov]
- LER File

S:\DNMS\INMIB\LERs\2011\7&8-2011.doc

ADAMS	<input type="checkbox"/> No	<input checked="" type="checkbox"/> Yes	<input type="checkbox"/> SUNSI Review Complete	Reviewer Initials: JLT
	<input checked="" type="checkbox"/> Publicly Available		<input checked="" type="checkbox"/> Non-sensitive	
	<input type="checkbox"/> Non-publicly Available		<input type="checkbox"/> Sensitive	
<b>KEYWORD:</b> SUNSI Review Complete				
RIV:DNMS/NMSB-A		C:NMSB-A		
JLThompson		GMVasquez		
/RA/		/RA/		
08/23/2011		08/31/2011		

OFFICIAL RECORD COPY

T=Telephone

E=E-mail

F=Fax

**RIV DNMS LICENSEE EVENT REPORTS SUMMARY TABLE - AUGUST 2011**

ADAMS ML # or Event #	Event Date	Notification Date	Licensee	License Number	Reporting Requirement	Event Description	Assigned Inspector	Review Status
46450	12/2/2010	12/2/2010	Acuren	42-32443-01	10 CFR 30.50	Sealed source of Ir-192 failed to retract in Prudhoe Bay, Alaska during industrial radiography	Razo	Open
ML111510906	5/25/2011	5/26/2011	National Oceanic & Atmospheric Admin.	46-23463-01	License Condition	Leaking foil source of Nickel-63 in an ECD within gas chromatograph	Hanson	Open
46927	6/4/2011	6/5/2011	ENI US Operating Company	50-29411-01	10 CFR 30.50	Tracerco fixed gauge shutter malfunction	Munoz	Open
ML111920503	6/22/2011	7/8/2011	Acuren USA	42-32443-01	10 CFR 20.1301	Dose to member of public greater than 2mR in any one hour	Munoz	Open
46757 ML111510866 ML11235A879	4/15/2011	4/15/2011	TEAM Industrial Services, Inc.	42-32219-01	10 CFR 20.2201	Lost radiography camera during shipment containing 15 curies of Iridium-192	Poston	Closed
46466 ML112000392 ML111180037	12/2/2010	12/2/2010	Rio Tinto, Pacific Steel & Recycling	9999-0001 General License	10 CFR 20.2201	Discovery of a fixed nuclear gauge containing licensed material in a scrap yard	Razo	Closed
ML1235A883	6/29/2011	6/30/2011	Western S.D. Community Action Agency	General License	10 CFR 20.2201	Theft of Niton XRF lead paint analyzer w/ 14 mCi cadmium-109	Poston	Closed