



Fisher Controls International LLC  
301 South First Ave  
P.O. Box 190  
Marshalltown, Iowa 50158-0190  
USA  
T (641) 754-3011  
F (641) 754-2830

August 23, 2011

United States Nuclear Regulatory Commission  
Document Control Desk  
Washington, DC 20555-0001

Subject: Possible Foundry Welding Repair Issues Final Notification

Fisher Controls is providing this final notification per the requirements of 10CFR21.21(a).

On August 3, 2011, Fisher provided an interim report concerning an audit of one of Fisher Control's suppliers and the determination that weld rod certified by an ISO process (instead of ASME) might have been used for weld repair of castings intended for nuclear service.

Fisher and the supplier have completed the process of reviewing all orders affected by this issue and did not find any orders that used the subject non-conforming material.

Therefore, Fisher will not issue a notification per the requirements of 10CFR21.21(b), because the review determined that a failure to comply condition does not exist.

Regards,

Bill Fitzgerald  
Vice President, Nuclear Business Unit  
Emerson Process Management, Fisher Valve Division

Reference: NRC Event# 47123



JE19  
NRC