

Cataldo, Paul C

From: Ramirez Jr, Ovidio
Sent: Tuesday, April 06, 2010 2:49 PM
To: Cataldo, Paul C
Cc: Andreozzi, Vincent Joseph
Subject: CR-IP3-2010-00429 questions

Paul,

1. In CR-IP3-2010-00429 CA-00001 the CR referenced in the response was supposed to be CR-IP3-2010-00438, instead of 00448.
2. The contact associated with the same spring as contact 9-11 on relay 62-1/6A is a SPARE, contact 10-12 not used.
3. The section of procedure 3-PT-M62C associated with 62-1/6A was re-performed allowing the Agastat to be tested/actuated again, as specified in CR-IP3-2010-00438 under immediate action description. Once this was performed the 480V UV Relays Functioning light illuminated.

AH