

From: Bill Kearney (USA - Casper) [Bill.Kearney@uranium1.com]
Sent: Friday, September 23, 2011 3:50 PM
To: Glenn Mooney; Joe Hunter (joe.hunter@wyo.gov)
Cc: Tim McCullough (USA - Casper); Larry Arbogast (USA - Christensen Ranch); Mike O'Leary (USA - Casper); Pablo Avila (USA - Casper); Donna Wichers (USA - Casper); Spitzberg, Blair; Gersey, Linda; Linton, Ron
Subject: Sept 23 , 2011 Release of Injection Fluid at Willow Creek ISR Facility

Glenn/Joe:

This email is to inform you that there was a release of injection fluid at the Willow Creek ISR facility operated by Uranium One. The release occurred today (September 23, 2011) at approximately 0900. The release occurred as a result of a broken fitting on the booster pump inside the MU-7 Module Building. Some of the released fluid was retained within the lined basement of the building. It is estimated that 2000 gallons was retained in the building basement and approximately 2000 gallons was released from the building and flowed about 200 ft into the wellfield area. Less than 0.04 acre was covered. No released fluid went into water or a drainage channel. The fluid in the building was recovered with a Vac Truck. The fluid released to the surface all soaked into the ground.

A sample of the released injection fluid was obtained for onsite lab analysis. An investigation in to the direct causes of the event will be completed. A more detailed written report will be submitted within 5 days (by September 28, 2011).

Please contact me if you need any more details.

Regards

Bill Kearney
Director of Safety, Health & Environment (SHE)
Uranium One Americas

907 North Poplar
Suite 260
Casper, WY 82601
Phone: 307-234-8235 ext. 329
Cell: 307-277-2618



This email, including any attachments, is confidential and may be privileged. Please check any attachments for viruses before opening them. If you are not the intended recipient, then any disclosure, copying, distribution or use of this email or any attachment, other than to or by the sender, is prohibited. If you received this email in error, please notify us immediately by returning it to the sender and delete this copy from your system.