

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER
INCIDENT REPORT

TO:

Mr. J. G. Keppler

FROM:
Northern States Power Company
Minneapolis, Minnesota
L. O. Mayer

DATE OF DOCUMENT

9/10/76

DATE RECEIVED

9/28/76

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED
One signed copy

DESCRIPTION

Ltr. trans the following:

**ACKNOWLEDGED
DO NOT REMOVE**

(1-P)

PLANT NAME:
Monticello

ENCLOSURE

Licensee Event Report (RO 50-263/76-14) on 8/11/76 concerning failure to meet Containment Inerting Requirements within 24 hours of switching to run mode.

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED SEND DIRECTLY TO KREGER/J. COLLINS

FOR ACTION/INFORMATION 9/29/76

RJL

BRANCH OFFICE:
W/3 CYS FOR ACTION

LIC. ASST.:
W/1 CYS

ACRS 16 CYS ~~HOLDING~~/SENT TO IA

Ziemann

Diggs

INTERNAL DISTRIBUTION

REG-FILE

NRC PDR

I & E (2)

MIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

GRIMES

CASE

BUTLER

HANAUER

PEDESCO/MACCARY

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

EXTERNAL DISTRIBUTION

LPDR: Minneapolis, MN

TIC:

NSIC:

CONTROL NUMBER

9836

NSP

D. Larson

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA *Regulatory*



September 10, 1976

Mr J G Keppler, Director, Region III
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Failure to meet Containment Inerting Requirements
Within 24 Hours of Switching to Run Mode

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are 3 copies.

Yours very truly,

L. O. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/ak

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
G Charnoff
MPCA
Attn: J W Ferman

9836

