

REPORT OF ABNORMAL OCCURRENCE AND/OR INCIDENT

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL (TEMPORARY FORM)

CONTROL NO: 10500

FILE: INCIDENT REPORT FILE

FROM: Northern States Power Co. Minneapolis, Minnesota L.O. Mayer			DATE OF DOC 9-30-75	DATE REC'D 10-3-75	LTR XXX	TWX	RPT	OTHER
TO: Mr. R.S. Boyd			ORIG 1 Signed	CC 39	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 40		DOCKET NO: 50-263		

DESCRIPTION:
Letter trans the following.....

ENCLOSURES:
Licensee Event Report # 75-19, on 9-21-75
Concerning Low SRM Count Rate.....

(40 Copies Enclosure Received)

PLANT NAME: Monticello

FOR ACTION/INFORMATION

SAB 10-6-75

BUTLER (L) W/ Copies	SCHWENCER (L) W/ Copies	ZIEMANN (L) W/ Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
PARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC ASST</u>	<u>A/T IND</u>
NRC PDR	SCHROEDER	**GRIMES	R. DIGGS (L)	BRAITMAN
OGC, ROOM P-506A	MACCARY	GAMMILL	H. GEARIN (L)	SALTZMAN
GOSSICK/STAFF	KNIGHT	KASTNER	E. GOULBOURNE (L)	MELTZ
CASE	PAWLICKI	BALLARD	P. KREUTZER (E)	
GIAMBUSSO	SHAO	SPANGLER	J. LEE (L)	<u>PLANS</u>
BOYD	**STELLO		M. RUSHBROOK (L)	MCDONALD
MOORE (L)	**HOUSTON	<u>ENVIRO</u>	S. REED (E)	CHAPMAN
DEYOUNG (L)	**NOVAK	MULLER	M. SERVICE (L)	DUBE (Ltr)
SKOVHOLT (L)	ROSS	DICKER	S. SHEPPARD (L)	E. COUPE
GOLLER (L) (Ltr)	IPPOLITO	KNIGHTON	M. SLATER (E)	PETERSON
P. COLLINS	TEDESCO	YOUNGBLOOD	H. SMITH (L)	HARTFIELD (2)
DENISE	J. COLLINS	REGAN	S. TEETS (L)	KLECKER
REG OPR	LAINAS	PROJECT LDR	G. WILLIAMS (E)	EISENHUT
FILE & REGION (2)	BENAROYA		V. WILSON (L)	*WIGGINTON
MIPC/PE (3)	VOLLMER	HARLESS	R. INGRAM (L)	F. WILLIAMS
STEELE			M. DUNCAN (E)	HANAUER


EXTERNAL DISTRIBUTION

1 - LOCAL PDR Minneapolis, Minn.	1 - NATIONAL LABS	1 - PDR-SAN/LA/NY
1 - TIC (ABERNATHY) (1)(2)(10)	1 - W. PENNINGTON, Rm E-201 GT	1 - BROOKHAVEN NAT LAB
1 - NSIC (BUCHANAN)	1 - CONSULTANTS	1 - G. ULRIKSON, ORNL
1 - ASLB	NEWMARK/BLUME/AGBABIAN	1 - AGMED (RUTH GUSSMAN) Rm B-127 GT
1 - Newton Anderson		1 - J. D. RUNKLES, Rm E-201 GT
5 - ACRS SENT TO LIC ASST R, Diggs		
** SEND ONLY TEN DAY REPORTS		

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401



September 30, 1975

Mr R S Boyd, Acting Director
Division of Reactor Licensing
U S Nuclear Regulatory Commission
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Low SRM Count Rate

The Licensee Event Report for this occurrence is reproduced on the back of this letter.

Yours very truly,

DM Mayer for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/ak

cc: J G Keppler
G Charnoff
MPCA
Attn: J W Ferman

10500

LICENSEE EVENT REPORT

CONTROL BLOCK:

1	2	3	4	5	6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER						LICENSE TYPE				EVENT TYPE				
01	M	N	M	N	P	1	00	-	00	00	00	00	-	00	41	11	11	01		
7	B	9				14	15							25	26			30	31	32

CON'T		CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE			
01		P	0	T	L	050	-	02	63	09	21	75	09	30	75		
7	8	57	58	59	60	61			68	69			74	75	80		

EVENT	DESCRIPTION
1	10/10/2010
2	10/10/2010
3	10/10/2010
4	10/10/2010
5	10/10/2010
6	10/10/2010
7	10/10/2010
8	10/10/2010
9	10/10/2010
10	10/10/2010
11	10/10/2010
12	10/10/2010
13	10/10/2010
14	10/10/2010
15	10/10/2010
16	10/10/2010
17	10/10/2010
18	10/10/2010
19	10/10/2010
20	10/10/2010
21	10/10/2010
22	10/10/2010
23	10/10/2010
24	10/10/2010
25	10/10/2010
26	10/10/2010
27	10/10/2010
28	10/10/2010
29	10/10/2010
30	10/10/2010
31	10/10/2010
32	10/10/2010
33	10/10/2010
34	10/10/2010
35	10/10/2010
36	10/10/2010
37	10/10/2010
38	10/10/2010
39	10/10/2010
40	10/10/2010
41	10/10/2010
42	10/10/2010
43	10/10/2010
44	10/10/2010
45	10/10/2010
46	10/10/2010
47	10/10/2010
48	10/10/2010
49	10/10/2010
50	10/10/2010
51	10/10/2010
52	10/10/2010
53	10/10/2010
54	10/10/2010
55	10/10/2010
56	10/10/2010
57	10/10/2010
58	10/10/2010
59	10/10/2010
60	10/10/2010
61	10/10/2010
62	10/10/2010
63	10/10/2010
64	10/10/2010
65	10/10/2010
66	10/10/2010
67	10/10/2010
68	10/10/2010
69	10/10/2010
70	10/10/2010
71	10/10/2010
72	10/10/2010
73	10/10/2010
74	10/10/2010
75	10/10/2010
76	10/10/2010
77	10/10/2010
78	10/10/2010
79	10/10/2010
80	10/10/2010
81	10/10/2010
82	10/10/2010
83	10/10/2010
84	10/10/2010
85	10/10/2010
86	10/10/2010
87	10/10/2010
88	10/10/2010
89	10/10/2010
90	10/10/2010
91	10/10/2010
92	10/10/2010
93	10/10/2010
94	10/10/2010
95	10/10/2010
96	10/10/2010
97	10/10/2010
98	10/10/2010
99	10/10/2010
100	10/10/2010

02 During refueling core alterations, the count rate of Source Range Monitor (SRM) 23
 03 decreased below 3 cps, the countrate required to consider the detector operable.
 04 With all other SRM's operable, fuel was re-loaded near the detector and nothing
 05 of safety significance occurred. This was a first-time event; an operational
 06 limit above 3 cps will be established to prevent similar future occurrences.

CAUSE DESCRIPTION

08 Nuclear fuel to sustain the required detector count rate was removed from the
 09 vicinity of the detector. Fuel was reloaded near the detector and SRM count
 10 rate was increased.

PERSONNEL EXPOSURES

NUMBER			TYPE	DESCRIPTION
13	000	Z	NA	

PERSONNEL INJURIES

PERSONNEL INFORMATION			DESCRIPTION	
NUMBER	DESCRIPTION	NUMBER	DESCRIPTION	
14	000	NA		

OFFSITE CONSEQUENCES

1	5	NA	80
---	---	----	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	NA

PUBLICITY

17	NA	80
----	----	----

[illegible]

7 8 9 (AO 50-263/75-19) 80

19 80

NAME: D E Nevinski

PHOTO (612) 295-5151 (ext. 118)