

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)**

CONTROL NO: 5488
FILE: INCIDENT REPORT FILE

FROM: Northern States Power Co. Minn. Minnesota L.O. Mayer			DATE OF DOC 5-15-75	DATE REC'D 5-19-75	LTR XXXX	TWX	RPT	OTHER
TO: A, Giambusso			ORIG NONE	CC	OTHER	SENT AEC PDR <u>XXXX</u> SENT LOCAL PDR <u>XXXX</u>		
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-263		

DESCRIPTION: Ltr. trans the following..... PLANT NAME: Monticello	ENCLOSURES: Abnorm. Occurr. # 75-08, on 5-5-75, concerning Inoperable RCIC Steam Supply Valve..... (1 cy. Encl. Rec'd)
---	--

FOR ACTION/INFORMATION

VCR 5-19-75

BUTLER (L) W/ Copies	SCHWENCER (L) ✓ W/ Copies	ZIEMANN (L) W/ 3 Copies	REGAN (E) W/ Copies
CLARK (L) W/ Copies	STOLZ (L) W/ Copies	DICKER (E) W/ Copies	LEAR (L) W/ Copies
FARR (L) W/ Copies	VASSALLO (L) W/ Copies	KNIGHTON (E) W/ Copies	SPELS W/ Copies
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLOOD (E) W/ Copies	

INTERNAL DISTRIBUTION


<u>REG FILE</u>	<u>TECH REVIEW</u>	<u>DENTON</u>	<u>LIC ASST</u>	<u>A/T IND.</u>
✓ NRC PDR	✓ SCHROEDER	✓ GRIMES	✓ R. DIGGS (L)	BRAITMAN
OGC, ROOM P-506A	✓ MACCARY	GAMMILL	H. GEARIN (L)	SALTZMAN
GOSSICK/STAFF	KNIGHT	KASTNER	E. GOULBOURNE (L)	MELTZ
✓ CASE	PAWLICKI	BALLARD	P. KREUTZER (E)	
GIAMBUSSO	SHAO	SPANGLER	J. LEE (L)	<u>PLANS</u>
BOYD	** STELLO		M. MAIGRET (L)	MCDONALD
MOORE (L)	** HOUSTON	<u>ENVIRO</u>	S. REED (E)	CHAPMAN
DEYOUNG (L)	** NOVAK	MULLER	M. SERVICE (L)	DUBE (Ltr)
SKOVHOLT (L)	✓ ROSS	DICKER	S. SHEPPARD (L)	E. COUPE
GOLLER (L) (Ltr)	✓ IPPOLITO	KNIGHTON	M. SLATER (E)	PETERSON
P. COLLINS	✓ TEDESCO	YOUNGBLOOD	H. SMITH (L)	HARTFIELD (2)
DENISE	LONG	REGAN	S. TEETS (L)	✓ KLECKER
REG OPR	LAINAS	PROJECT LDR	G. WILLIAMS (E)	EISENHUT
✓ FILE & REGION (2)	BENAROYA		V. WILSON (L)	WIGGINTON
✓ MIPC/PE (3)	✓ VOLLMER	HARLESS	R. INGRAM (L)	✓ F. WILLIAMS
STEELE				✓ HANAUER

EXTERNAL DISTRIBUTION

1 - LOCAL PDR <i>Minneapolis Minn.</i> 1 - TIC (ABERNATHY) (1)(2)(10) 1 - NSIC (BUCHANAN) 1 - ASLB 1 - Newton Anderson 1 - ACRS SENT TO LIC ASST ** SEND ONLY TEN DAY REPORTS	1 - NATIONAL LABS 1 - W. PENNINGTON, Rm E-201 GT 1 - CONSULTANTS NEWMARK/BLUME/AGBABIAN	1 - PDR-SAN/LA/NY 1 - BROOKHAVEN NAT LAB 1 - G. ULRIKSON, ORNL 1 - AGMED (RUTH GUSSMAN) Rm B-127 GT 1 - J. D. RUNKLES, Rm E-201 GT
---	--	---

May 15, 1975

Mr. A. Giambusso, Director ✓
Division of Reactor Licensing
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555



Dear Mr. Giambusso:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Licensee Event Report to the NRC
Inoperable RCIC Steam Supply Valve

The Licensee Event Report for this occurrence is reproduced on the back of this letter.

Yours very truly,

L. O. Mayer, PE
Manager, Nuclear Support Services

cc: J. G. Kepper
G. Charnoff
Minnesota Pollution Control Agency
Attn: E. A. Pryzina

5488

LICENSEE EVENT REPORT

CONTROL BLOCK:
16

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME 7 8 9 14 15 25 26 30 31 32													
LICENSE NUMBER 7 8 9 14 15 25 26 30 31 32													
LICENSE TYPE 7 8 9 14 15 25 26 30 31 32													
EVENT TYPE 7 8 9 14 15 25 26 30 31 32													

CATEGORY 7 8 9 14 15 25 26 30 31 32													
REPORT TYPE 7 8 9 14 15 25 26 30 31 32													
REPORT SOURCE 7 8 9 14 15 25 26 30 31 32													
DOCKET NUMBER 7 8 9 14 15 25 26 30 31 32													
EVENT DATE 7 8 9 14 15 25 26 30 31 32													
REPORT DATE 7 8 9 14 15 25 26 30 31 32													

EVENT DESCRIPTION

7 8 9 14 15 25 26 30 31 32													
7 8 9 14 15 25 26 30 31 32													
7 8 9 14 15 25 26 30 31 32													
7 8 9 14 15 25 26 30 31 32													
7 8 9 14 15 25 26 30 31 32													

SYSTEM CODE 7 8 9 14 15 25 26 30 31 32													
CAUSE CODE 7 8 9 14 15 25 26 30 31 32													
COMPONENT CODE 7 8 9 14 15 25 26 30 31 32													
PRIME COMPONENT SUPPLIER 7 8 9 14 15 25 26 30 31 32													
COMPONENT MANUFACTURER 7 8 9 14 15 25 26 30 31 32													
VIOLATION 7 8 9 14 15 25 26 30 31 32													

CAUSE DESCRIPTION

7 8 9 14 15 25 26 30 31 32													
7 8 9 14 15 25 26 30 31 32													
7 8 9 14 15 25 26 30 31 32													

FACILITY STATUS 7 8 9 14 15 25 26 30 31 32													
% POWER 7 8 9 14 15 25 26 30 31 32													
OTHER STATUS 7 8 9 14 15 25 26 30 31 32													
METHOD OF DISCOVERY 7 8 9 14 15 25 26 30 31 32													
DISCOVERY DESCRIPTION 7 8 9 14 15 25 26 30 31 32													

FORM OF ACTIVITY RELEASED 7 8 9 14 15 25 26 30 31 32													
CONTENT OF RELEASE 7 8 9 14 15 25 26 30 31 32													
AMOUNT OF ACTIVITY 7 8 9 14 15 25 26 30 31 32													
LOCATION OF RELEASE 7 8 9 14 15 25 26 30 31 32													

PERSONNEL EXPOSURES

NUMBER 7 8 9 14 15 25 26 30 31 32													
TYPE 7 8 9 14 15 25 26 30 31 32													
DESCRIPTION 7 8 9 14 15 25 26 30 31 32													

PERSONNEL INJURIES

NUMBER 7 8 9 14 15 25 26 30 31 32													
DESCRIPTION 7 8 9 14 15 25 26 30 31 32													

OFFSITE CONSEQUENCES

7 8 9 14 15 25 26 30 31 32													
---	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE 7 8 9 14 15 25 26 30 31 32													
DESCRIPTION 7 8 9 14 15 25 26 30 31 32													

PUBLICITY

7 8 9 14 15 25 26 30 31 32													
---	--	--	--	--	--	--	--	--	--	--	--	--	--

ADDITIONAL FACTORS

7 8 9 14 15 25 26 30 31 32													
---	--	--	--	--	--	--	--	--	--	--	--	--	--

7 8 9 14 15 25 26 30 31 32													
---	--	--	--	--	--	--	--	--	--	--	--	--	--

NAME: BYRON D. DA PHONE: 612/295-5151

NSP


NORTHERN STATES POWER COMPANY

**Monticello Nuclear Generating Plant
Monticello, Minnesota 55362**

5/15/75

#5488

May 5, 1975



Mr. J. G. Keppler, Director
Region III
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Bllyn, Illinois 60137

Dear Mr. Keppler:

**MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22**

On May 5, 1975, it was discovered that the control circuit for valve MD-2078, Steam Supply to RCIC Turbine, was de-energized. Investigation revealed that the motor control unit undervoltage relay coil had opened. The coil was replaced and remote operability of the valve was demonstrated. Further investigation of the occurrence is continuing.

Yours very truly,

A handwritten signature in cursive script, appearing to read 'C. E. Larson'.

C. E. Larson
Plant Manager
Monticello Nuclear Generating Plant

CEL/kik

cc: A Giambusso
G Charnoff
Minnesota Pollution Control Agency
Attn: E A Pryzina
File