

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 6417

FILE: B40

FROM: Northern States Power Company Monticello, Minnesota 55362 C. E. Larson			DATE OF DOC: 7-15-74	DATE REC'D 7-15-74	LTR	TWX	RPT	OTHER Facsimile
TO: Mr. Keppler			ORIG 1	CC	OTHER	SENT AEC PDR <u>X</u> SENT LOCAL PDR <u>X</u>		
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D 1		DOCKET NO: 50-263		
	XXXX							

DESCRIPTION:
Facsimile, reporting an Abnormal Occurrence on 7-12-74, concerning the failure of the No. 1 RHR Service Water Pump to Start.....

ENCLOSURES:

Do Not Remove

PLANT NAME: Monticello

FOR ACTION/INFORMATION 7-15-74 AB

- | | | | |
|------------------------|---------------------------|--|-----------------------|
| BUTLER(L)
W/ Copies | SCHWENCER(L)
W/ Copies | <input checked="" type="checkbox"/> ZIEMANN(L)
W/7 Copies | REGAN(E)
W/ Copies |
| CLARK(L)
W/ Copies | STOLZ(L)
W/ Copies | DICKER(E)
W/ Copies | LEAR(L)
W/ Copies |
| FAER(L)
W/ Copies | VASSALLO(L)
W/ Copies | KNIGHTON(E)
W/ Copies | W/ Copies |
| KNIEL(L)
W/ Copies | PURPLE(L)
W/ Copies | YOUNGBLOOD(E)
W/ Copies | W/ Copies |

INTERNAL DISTRIBUTION

- | | | | | |
|--|---|----------------|---|---|
| <input checked="" type="checkbox"/> REG FILE | <u>TECH REVIEW</u> | DENTON | <u>LIC ASST</u> | <u>A/T IND</u> |
| <input checked="" type="checkbox"/> AEC PDR | <input checked="" type="checkbox"/> HENDRIE | GRIMES | | BRAITMAN |
| <input checked="" type="checkbox"/> OGC, ROOM P-506A | <input checked="" type="checkbox"/> SCHROEDER | GAMMILL | <input checked="" type="checkbox"/> DIGGS (L) | SALTZMAN |
| <input checked="" type="checkbox"/> MUNTZING/STAFF | <input checked="" type="checkbox"/> MACCARY | KASTNER | GEARIN (L) | B. HURT |
| <input checked="" type="checkbox"/> CASE | <input checked="" type="checkbox"/> KNIGHT | BALLARD | GOULBOURNE (L) | <u>PLANS</u> |
| GIAMBUSO | <input checked="" type="checkbox"/> PAWLICKI | SPANGLER | KREUTZER (E) | MCDONALD |
| BOYD | <input checked="" type="checkbox"/> SHAO | | LEE (L) | CHAPMAN |
| MOORE (L)(BWR) | <input checked="" type="checkbox"/> STELLO | <u>ENVIRO</u> | MAIGRET (L) | DUBE w/input |
| DEYOUNG(L)(FWR) | <input checked="" type="checkbox"/> HOUSTON | MULLER | REED (E) | E. COUPE |
| SKOVHOLT (L) | <input checked="" type="checkbox"/> NOVAK | DICKER | SERVICE (L) | |
| <input checked="" type="checkbox"/> COLLER(L) | <input checked="" type="checkbox"/> ROSS | KNIGHTON | SHEPPARD (L) | <input checked="" type="checkbox"/> D. THOMPSON (2) |
| P. COLLINS | <input checked="" type="checkbox"/> IPPOLITO | YOUNGBLOOD | SLATER (E) | <input checked="" type="checkbox"/> ZLECKER |
| DENISE | <input checked="" type="checkbox"/> TEDESCO | REGAN | SMITH (L) | <input checked="" type="checkbox"/> EISENHUT |
| REG OPR | <input checked="" type="checkbox"/> LONG | PROJECT LDR | TEETS (L) | |
| <input checked="" type="checkbox"/> FILE & REGION(3) | <input checked="" type="checkbox"/> LAINAS | | WILLIAMS (E) | |
| <input checked="" type="checkbox"/> MORRIS | <input checked="" type="checkbox"/> BENAROYA | <u>HARLESS</u> | WILSON (L) | |
| <input checked="" type="checkbox"/> STEELE | <input checked="" type="checkbox"/> VOLLMER | | | |

EXTERNAL DISTRIBUTION

- | | | |
|--|---------------------------------|------------------------|
| <input checked="" type="checkbox"/> 1 - LOCAL PDR <u>Minneapolis, Minn.</u> | (1)(2)(10)-NATIONAL LAB'S | 1-PDR-SAN/LA/NY |
| <input checked="" type="checkbox"/> 1 - TIC (ABERNATHY) | 1-ASLBP(E/W Bldg, Rm 529) | 1-LIBRARIAN |
| <input checked="" type="checkbox"/> 1 - NSIC(BUCHANAN) | 1-W. PENNINGTON, Rm E-201 GT | BROOKHAVEN NAT. LAB |
| 1 - ASLB | 1-CONSULTANT'S | 1-ACMED(Ruth Gussman) |
| 1 - P. R. DAVIS (AEROJET NUCLEAR) | NEWARK/BLUME/AGBBIAN | RM-B-127, GT. |
| <input checked="" type="checkbox"/> 16 - CYS ACRS XXXXXX SENT TO LIC ASST.
R. DIGGS FOR DIST | 1-GERALD ULRIKSON...ORNL | 1-RD..MULLER..F-309 GT |
| | 1-B & M SWINEBROAD, Rm E-201 GT | |

NSP**NORTHERN STATES POWER COMPANY**

Monticello, Minnesota 55362

July 15, 1974

Mr. J. G. Keppler, Regional Director
 Directorate of Regulatory Operations
 Region III
 United States Atomic Energy Commission
 799 Roosevelt Road
 Glen Ellyn, Illinois 61073



Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
 Docket No. 50-263 License No. DPR-22

Failure of the No. 11 RHR Service Water Pump to Start


On July 12, 1974, during routine operation of the RHR Service Water system, for torus cooling, the No. 11 RHR SW pump failed to start. The pump motor breaker was replaced with a spare and the pump was demonstrated operable. The redundant pump in the "A" loop and the pumps in the redundant "B" loop were also demonstrated to be operable. An investigation to determine the cause of the breaker malfunction is in progress.

Yours very truly

G. E. Larson
 Plant Manager

CHL/mmnn

cc: J F O'Leary, Directorate of Licensing
 G Charnoff
 Minnesota Pollution Control Agency
 Attn: E A Pryzina
 File



Copies sent by telecopier to Keppler and O'Leary

6417