

AEC DISTRIBUTION FOR PART 50 DOCKET MATERIAL
(TEMPORARY FORM)

CONTROL NO: 3226

FILE: 410

FROM: Northern States Power Co. Monticello, Minnesota C. E. Larson		DATE OF DOC 4-11-74	DATE REC'D 4-12-74	LTR	MEMO	RPT	OTHER TWX
TO: J. G. Képpler		ORIG	CC 1	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX		
CLASS	UNCLASS XXX/	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-263		

DESCRIPTION:
Twx furn info re abnormal occurrence 4-10-74 re broken Stem on RHR Service Water Control Valve, CV-1728

ENCLOSURES:

DO NOT REMOVE

ACKNOWLEDGED

PLANT NAME: MONTICELLO

FOR ACTION/INFORMATION 4-12-74 GMC

BUTLER(L) W/ Copies	SCHWENCER(L) W/ Copies	✓ ZIEMANN(L) W/ 7 Copies	REGAN(E) W/ Copies
CLARK(L) W/ Copies	STOLZ(L) W/ Copies	DICKER(E) W/ Copies	W/ Copies
GOLLER(L) W/ Copies	VASSALLO(L) W/ Copies	KNIGHTON(E) W/ Copies	W/ Copies
KNIEL(L) W/ Copies	SCHEMEL(L) W/ Copies	YOUNGBLOOD(E) W/ Copies	W/ Copies

INTERNAL DISTRIBUTION

✓ <u>REG FILE</u> ✓ AEC PDR ✓ OGC, ROOM P-506A ✓ MUNTZING/STAFF ✓ CASE GIAMBUSO BOYD MOORE (L)(BWR) DEYOUNG(L)(PWR) ✓ SKOVHOLT (L) P. COLLINS DENISE ✓ REG OPR ✓ FILE & REGION(3) ✓ MORRIS ✓ STEELE	✓ <u>TECH REVIEW</u> ✓ HENDRIE ✓ SCHROEDER ✓ MACCARY ✓ KNIGHT ✓ PAWLICKI ✓ SHAO ✓ STELLO ✓ HOUSTON ✓ NOVAK ✓ ROSS ✓ IPPOLITO ✓ TEDESCO ✓ LONG ✓ LAINAS ✓ BENAROYA ✓ VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER <u>ENVIRO</u> MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR HARLESS	<u>LIC ASST</u> ✓ DIGGS (L) GEARIN (L) GOULBOURNE (L) LEE (L) MAIGRET (L) REED (E) SERVICE (L) SHEPPARD (L) SLATER (E) SMITH (L) TEETS (L) WADE (E) WILLIAMS (E) WILSON (L)	<u>A/T IND</u> BRAITMAN SALTZMAN B. HURT <u>PLANS</u> MCDONALD DUBE w/Input <u>INFO</u> C. MILES ✓ B. KING ✓ KLECKER ✓ EISENHUT
--	---	---	---	--

EXTERNAL DISTRIBUTION

✓ 1 - LOCAL PDR MINNEAPOLIS, MINN	(1) (2) (10) - NATIONAL LAB'S	1 - PDR-SAN/LA/NY
✓ 1 - DTIE (ABERNATHY)	1 - ASLBP (E/W Bldg, Rm 529)	1 - GERALD LELLOUCHE
✓ 1 - NSIC (BUCHANAN)	1 - W. PENNINGTON, Rm E-201 GT	BROOKHAVEN NAT. LAB
✓ 1 - ASLB (YORE)	1 - CONSULTANT'S	1 - AGMED (Ruth Gussman)
✓ 16 - CYS ACRS HOLDING	NEWMARK/BLUME/AGBABIAN	RM-B-127, GT.
Sent to Lic Asst Diggs 4-12-74	1 - GERALD ULRIKSON... ORNL	1 - RD..MULLER..F-309 GT

Pg.

NSP

Regulatory


File Cy.

NORTHERN STATES POWER COMPANY

Monticello, Minnesota 55362

April 11, 1974

Mr. J. G. Keppler, Regional Director
Directorate of Regulatory Operations
Region III
United States Atomic Energy Commission
799 Roosevelt Road
Glen Ellyn, Illinois 61073



Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

**Broken Stem on RHR Service
Water Control Valve, CV-1728**

On April 10, 1974, an inspection of the RHR Service Water control valve, CV-1728, revealed that the valve stem was broken. The nature of the failure and design of the valve are such that the valve was still able to perform its function of controlling differential pressure between the RHR and RHR Service Water.

An investigation into the cause of this occurrence is continuing.

Yours very truly,

A handwritten signature in cursive that reads "C. E. Larsen".

C. E. Larsen
Plant Manager

CEL/mm

cc: J F O'Leary, Directorate of Licensing
G Charnoff
Minnesota Pollution Control Agency
Attn: E A Pryzina
File



Copies sent by telecopier to Keppler and O'Leary

3226