## IBUTION FOR PART 50 DOCKET MAT

(TEMPORARY FORM)

2558

CONTROL	NO:	2550
. מדדם	AlD	

							LIL	· · / /	
FROM: Northern States Power Company Monticello, Minn. 55362 Mr. C.E. Larson		DATE OF DOC 3-25-74	DATE REC'D 3-25-74		LTR	MEMO	RPT	OTHER FACIMILE	
TO:	Keppler		ORIG 1	CC	OTHER	SENT AEC PDR XXX SENT LOCAL PDR XXX			
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CY	S REC'D	DOCKET NO: 50-263			
					ACTION OF				

DESCRIPTION:

BUTLER (L)

Facimile reporting an abnormal occurrence at the Monticello Nuclear Plant concerning ... Reactor LOW Low Water Level-ECCS Initiating Switch Malfunction \*

SCHWENCER(L)

ENCLOSURES:

REGAN(E)

## DO NOT REMOVE

3-26-74

JB

PLANT NAME: Monticello

W/ Copies	W/ Copies	W/7 Copies	W/ Copies	
CLARK(L)	STOLZ(L)	DICKER(E)	c*	
W/ Copies	W/ Copies	W/ Copies	W/ Copies	
GOLLER(L)	VASSALLO(L)	KNIGHTON(E)		•
W/ Copies	W/ Copies	W/ Copies	W/ Copies	
KNIEL(L)	SCHEMEL(L)	YOUNGBLOOD (E)		
· · · · · · · · · · · · · · · · · · ·	W/ Copies	W/ Copies	W/ Copies	
		INTERNAL DISTRIBUT	rion	
REG FILE	TECH REVIEW	DENTON	7 * 0 . 1 O O M	A/T IND
AEC PDR	HENDRIE	GRIMES	LIC ASST	BRAITMAN
✓OGC, ROOM P-506A	SCHROEDER	GAMMILL -	DIGGS (L)	SALTZMAN
✓MUNTZING/STAFF	✓MACCARY	KASTNER	GEARIN (L)	B. HURT
✓ CASE	✓ KNIGHT	BALLARD	GOULBOURNE (L)	PLANS
GLAMBUSSO	<b>✓</b> PAWLICKI	SPANGLER	LEE (L)	MCDONALD
BOYD	✓SHAO		MAIGRET (L)	DUBE w/Input
MOORE (L) (BWR)	✓STELLO	ENVIRO	SERVICE (L)	DOBE W/ Input
DEYOUNG(L)(PWR)	✓ HOUS TON	MULLER	SHEPPARD (E)	INFO
SKOVHOLT (L)	NOVAK	DICKER	SMITH (L)	C. MILES
P. COLLINS	ROSS	KNIGHTON	TEETS (L)	✓ B. KING
DENISE	/IPPOLITO	YOUNGBLOOD	WADE (E)	
REG OPR	<b>✓</b> TEDESCO	REGAN	WILLIAMS (E)	
FILE & REGION(3)	LONG	PROJECT LDR	WILSON (L)	·
MORRIS	LAINAS	2	S. REED (L)	•
STEELE	BENAROYA	HARLESS		
	✓ VOLLMER			0.

FOR ACTION/INFORMATION

ZIEMANN(L)

1 - LOCAL PDR //Monneapol'is /Minn.

✓1 - DTIE(ABERNATHY)

- NSIC (BUCHANAN)

1 - ASLB(YORE/SAYRE/ WOODARD/"H" ST.

✓ 16 - CYS ACRS HOWXXXXX Sent to Diggs Jan La Marian

3-26-74

(1)(2)(10)-NATIONAL LAB'S

EXTERNAL DISTRIBUTION

1-ASLBP(E/W Bldg, Rm 529)

1-W. PENNINGTON, Rm E-201 GT

1-CONSULTANT'S

NEWMARK/BLUME/AGBABIAN

1-GERALD ULRIKSON...ORNL

1-PDR-SAN/LA/NY

1-GERALD LELLOUCHE

BROOKHAVEN NAT. LAB

1-AGMED (Ruth Gussman)

RM-B-127, GT.

1-RD..MULLER..F-309 GT

DCCKETED MAR 25 1974

REGULATORY



## Monticello, Minnesota 55362

March 25, 1974

Mr. J. G. Keppler, Regional Director Directorate of Regulatory Operations Region III United States Atomic Energy Commission 799 Roosevelt Read Glen Ellyn, Illinois 61073

Dear Mr. Keppler:

MONTICELLO NICLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Reactor Low Low Water Level-ECCS Initiating Switch Malfunction

A condition occurred at the Monticello Nuclear Generating Plant which we are reporting to your office in accordance with Section 6.7.B.1. Abnormal Occurrence Reports, of Appendix A, Technical Specifications, of Provisional Operating License DPR-22.

On March 22, 1974, while performing a routine surveillance test, one of two switches on one of the four "Reactor Low Low Level-ECCS Initiation" instruments was found failed in the untripped state. At the time the switch malfunction was discovered, the plant was in a cold shutdown condition for reactor refueling operations. The cause of the malfunction has not been identified; however, as a precautionary measure, the switch was replaced, and the instrument was calibrated. Satisfactory repeatable operation of the switch was demonstrated in subsequent testing of the instrument. The instrument involved has been placed on an accelerated eight week surveillance test schedule.

The switch malfunction did not result in an unsafe plant condition since redundant instruments were found to trip at the desired trip setting and would have provided the required ECCS initiation function at the desired trip setting.

Yours very truly.

Plant Manager

CEL/man

cc: J F O'Leary, Directorate of Licensing G Charnoff Minnesota Pollution Control Agency

Attn: E A Pryzina

File

