NRC FORM 591M PA (10-2010)	RT 1			U.S. NUCLE	AR REGULATOR	Y COMMISSION			
10 CFR 2.201	SAFETY INSPECTION	REPORT A	ND COMPLIA	ANCE INSPI	ECTION				
LICENSEE/LOCATION INSPECTED: Ray County Memorial Hospital		2. NRC/REGION/	2. NRC/REGIONAL OFFICE						
904 Wollard Blvd.		Danian III. 2	Region III: 2443 Warrenville Rd., Ste. 210 Lisle, IL 60532-4352						
Richmond, MO 64085		Region III. 22	Region III. 2443 Waitenville Ru., Ste. 210 Liste, IL 00332-4332						
DEDODE NUMBER		,							
REPORT NUMBER(S)		4. LICENSE NUM	IDED/S\	ls D	ATE(S) OF INSPEC	STION			
030-14777	3. DOCKET NUMBER(S) 030-14777		IDER(S)		ct, 5, 20				
LICENSEE:					00,0,00				
The inspection was an Regulatory Commission	examination of the activities conducte on (NRC) rules and regulations and the sentative records, interviews with person	e conditions of you	ir license. The inspe	ection consisted of	selective examin	ations of			
1. Based on	the inspection findings, no violations w	ere identified.							
2. Previous v	Previous violation(s) closed.								
non-repeti	ons(s), specifically described to you by tive, and corrective action was or is be were satisfied.	y the inspector as ling taken, and the	non-cited violations, remaining criteria in	, are not being cite n the NRC Enforce	d because they w ment Policy, to e	vere self-identified, xercise			
	Non-cited violation(s) were discuss	ed involving the fo	ollowing requirement	t(s):	·				
					•				
		•							
٠					·				
-			. •	À					
4. During this cited. This	s inspection, certain of your activities, a s form is a NOTICE OF VIOLATION, w	as described belov which may be subj	w and/or attached, w ect to posting in acc	vere in violation of ordance with 10 C	NRC requiremen FR 19.11.	ts and are being			
(Violations	and Corrective Actions)			¥ .					
	•								
,									
			•						
			*						
	Å								
	4								
l beaution at the start			rective Actions						
corrective actions is n	thin 30 days, the actions described by nade in accordance with the requireme ance will be achieved). I understand th	ents of 10 CFR 2.2	201 (corrective steps	s already taken, co	rrective steps wh	ich will be taken,			
TITLE	PRINTED NAME			SIGNATURE		DATE			
LICENSEE'S REPRESENTATIVE									
NRC INSPECTOR	Deborah A. Piskura		Delos A	A Pokus		10/5/2011			
BRANCH CHIEF	Tamara E. Bloomer		1	10		11/1			

NRC FORM 591M PART (10-2010) 10 CFR 2.201	3	Docket File Infe	ormation	U.S. NUCLEAR RE	GULATORY COMMISSION						
S	AFETY INSPEC	TION REPORT AND		CE INSPECTI	ON						
1. LICENSEE/LOCATION INSPECTED:		2. NRC/REGIONAL OFFICE									
Ray County Memorial Hospital		Region III: 244	Region III: 2443 Warrenville Rd., Ste. 210 Lisle, IL 60532-4352								
REPORT NUMBER(S) 2011-001											
3. DOCKET NUMBER(S) 030-14777		4. LICENSE NUMBE 24-18279-01	4. LICENSE NUMBER(S) 24-18279-01		5. DATE(S) OF INSPECTION 10/05/2011						
6. INSPECTION PROCEDURES USED 87130		7. INSPECTION FOO 03.01 - 03.07	7. INSPECTION FOCUS AREAS 03.01 - 03.07								
SUPPLEMENTAL INSPECTION INFORMATION											
1. PROGRAM CODE(S) 02120	2. PRIORITY 3	3. LICENSEE CONT. Joseph Caresio,			ONE NUMBER (816) 470-5432						
✓ Main Office In	✓ Main Office Inspection Next Inspection Date: Oct. 2014										
Field Office In	spection	***************************************		menora.							
Temporary Jo	b Site Inspection										
		PROGRAM SO	OPE								
included a full spectrum of studies. The licensee received unit doses from a licensed radiopharmacy. Although the licensee was authorized for Section 35.300 material, the hospital had not administered these therapeutic procedures since the previous inspection. The radiation safety program was audited quarterly by the contractor's safety officer.  This inspection consisted of interviews with select licensee personnel; a review of select records; a tour of the nuclear medicine department; and independent measurements. The inspection included observations of dose calibrator QA checks, security of byproduct material, use of personnel											
monitoring, package recei	pts and surveys.										
	•										
ı											
	•										

NRC FORM 591M PART 3 (10-2010)