

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8512130194 DOC. DATE: 85/12/03 NOTARIZED: NO DOCKET #
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH. NAME AUTHOR AFFILIATION
 MUSOLF, D. Northern States Power Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Office of Nuclear Reactor Regulation, Director (post 851125)

SUBJECT: Forwards corrected Tech Specs Pages 164 & 165 to 820924
 application for amend to License DPR-22 re pressure
 suppression chamber-drywell vacuum breakers.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+2
 TITLE: OR Submittal: General Distribution

NOTES: 05000263
 DL: 09/08/70

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID	CODE/NAME	LTR	ENCL	ID	CODE/NAME	LTR	ENCL
	BWR PD1	PD 01	5	5				
INTERNAL:	ACRS	09	6	6	ADM/LFMB		1	0
	ELD/HDS1		1	0	NRR BWR EB		1	1
	NRR PWR-A	EB	1	1	NRR PWR-B EB		1	1
	NRR/DHFT/TSCB		1	1	NRR/DSRO DIR		1	1
	NRR/DSRO/RRAB		1	1	NRR/ORAB		1	0
	<u>REG FILE</u>	04	1	1	RGNS		1	1
EXTERNAL:	24X		1	1	EG&G BRUSKE, S		1	1
	LPDR	03	1	1	NRC PDR 02		1	1
	NSIC	05	1	1				

TOTAL NUMBER OF COPIES REQUIRED: LTR 27 ENCL 24



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

December 3, 1985

Director
Office of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
DOCKET NO. 50-263 LICENSE NO. DPR-22
Revision No. 3 to License Amendment
Request dated September 24, 1982

Attached are two corrected Exhibit B pages for our License Amendment Request dated September 24, 1982. The attached Exhibit B pages 164 and 165 should be substituted for page 164 of the original submittal.

These revised pages correct typographical errors and omissions in the original submittal. The original page 164 did not reflect changes authorized by Monticello License Amendment 8 on November 5, 1981. A required section relettering on page 165 was also omitted from the original submittal. We apologize for any inconvenience these errors may have caused.

The actual changes requested in our original submittal, as described in Exhibit A, are not affected by these errors.

A license amendment fee for this revision was determined to be unnecessary because it is a correction to a License Amendment Request for which a fee has already been paid.


David Musolf
Manager - Nuclear Support Services

c: Regional Administrator-III, NRC
Resident Inspector, NRC
NRR Project Manager, NRC
G Charnoff

Attachment

8512130194 851203
PDR ADOCK 05000263
P PDR

Aool
11