•	REGULATOR	NFORMATION	DISTRIBUTION SYNCE	M (RIDS)	
FACIL:50 AUTH.N/ MAYER.L	D-263 MONTICELLO # AME AUTHOR .O. NORTHERN NAME RECIPIE	AF, NORTHERN S AFFILIATION STATES POWER ENT AFFILIATION	2	: NO	DOCKET # 05000263
<ul> <li>SUBJECT: Responds to 780216 NRC ltr requesting addl info re reactor vessel matl surveillance prog.Dye to a delay by Gen Elec in assembling this info,util requests extension of time to provide info.</li> </ul>					
DISTRIBUTION CODE: A021S COPIES RECEIVED:LTR <u>1</u> ENCL <u>0</u> SIZE: <u>1</u> TITLE: REACTOR VESSEL MATERIAL SURVEILLANCE					
NOTES :		-			
• ACTLON:	RECIPIENT ID CODE/NAME O5 BC ORB#3 LA	LTTR ENCL	RECIPIENT ID CODE/NAME 08 ZWEIZIG	COPIES LTTR ENCL 1 1	•
• INTERNAL :	01 REG FILE 09 I&E 12 HANAUER 14 AD SYS/PROJ 16 REAC SFTY BR 18 EEB 20 HOGE 22 RANDALL OELD	1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	O2 NRC PDR 11 MIPC 13 MATL ENGR BR 15 ENGR BR 17 PLANT SYS BR 19 HAZELTON 21 GAMBLE,R MLYNCZAK,M.	1     1       1     1       1     1       1     1       1     1       1     1       1     1       1     1       1     1       1     1       1     1       1     1       1     1	•
EXTERNAL:	03 LPDR 23 ACRS	1 1 16 16	O4 NSIC	1 1	•

NED 72 1918

MA-4 B



## NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

December 11, 1978

Director of Nuclear Reactor Regulation U S Nuclear Regulatory Commission Washington, DC 20555

> MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Reactor Vessel Material Surveillance Program

In a letter dated February 16, 1978, from Mr D K Davis, Acting Chief, Operating Reactors Branch No. 2, Division of Operating Reactors, Northern States Power Company was requested to provide additional information concerning the reactor vessel material surveillance program at Monticello. Information we had previously supplied to the NRC Staff in our letters dated July 22, 1977, August 3, 1977 and September 1, 1977 was judged to be inadequate.

As noted in our letter dated August 16, 1978, General Electric is currently engaged in assembling the information requested by the NRC Staff. We stated in that letter that a submittal date of December 1, 1978 was planned.

General Electric has not yet completed the work necessary to provide the Staff with the information they requested. This delay is due to the unavailability of certain information from the vessel vendor and the need to research the records of the plate supplier. While no firm schedule is available at this time for supplying the necessary information, it appears that at least another three months will be required.

We will inform the Commission of any further delays in this work which would cause our schedule to be delayed further. Please contact us if you have any questions related to this matter.

L O Mayer, PE Manager of Nuclear Support Services

LOM/DMM/deh

7812140143

cc: J G Keppler G Charnoff

REGULATORY DOCKET FILE COPY