Y INFORMATION DISTRIBUTION YSTEM (RIDS)

DOC.DATE: 79/02/26 NOTARIZED: NO DOCKET # ACCESSION NBR:7903020339 FACIL:50-263 MONTICELLO NUCLEAR GENERATING PLANT, NORTHERN STATES 05000263

AUTH.NAME MAYER, L.O.

AUTHOR AFFILIATION

RECIP.NAME

ACTION:

23 ACRS

NORTHERN STATES POWER CO.

RECIPIENT AFFILIATION

OFFICE OF NUCLEAR REACTOR REGULATION

SUBJECT: FORWARDS REVISION 3 TO "ASME CODE SECTION XI INSERVICE INSP & TESTING PROGRAM & INFO REQUIRED FOR NRC REVIEW FOR RELIEF FROM ASME CODE SECTION XI REQUIREMENTS." REVISES INSERVICE

INSP & TESTING PROGRAM DESCRIPTION & REQUESTS FOR RELIEF.

DISTRIBUTION CODE: A001S COPIES RECEIVED: LTR 70 ENCL 40 SIZE: 3 SIZE: 37 TITLE: GENERAL DISTRIBUTION FOR AFTER ISSUANCE OF OPERATING LIC

NOTES: RECIPIENT COPIES RECIPIENT COPIES LITTR ENCL ID CODE/NAME LTTR ENCL ID CODE/NAME

05 BC ORB #3 7 7 REG FILE 02 NRC PDR INTERNAL: 2 14 TA/EDO ISE 2 15 CORE PERF BR 16 AD SYS/PROJ 1 17 ENGR BR 1 1 18 REAC SFTY BR 19 PLANT SYS BR 1 SO EER 21 EFLT TRT SYS 1 22 BRINKMAN 04 NSIC EXTERNAL: 03 LPDR 1 1

16

16

MAR 5 1979

NSP
NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

February 26, 1979

Director of Nuclear Reactor Regulation U S Nuclear Regulatory Commission Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Information Required for NRC Review of Inservice
Inspection and Testing Program and Requests for Relief from
ASME Code Section XI Requirements

Attached you will find 40 copies of Revision Number 3 to our report entitled, "ASME Code Section XI Inservice Inspection and Testing Program and Information Required for NRC Review for Relief from ASME Code Section XI Requirements." This is a revision of our inservice inspection and testing program description and requests for relief submitted to the Commission on March 15, 1978. Instructions are provided for entering Revision Number 3 in copies of the original report.

The purpose of this revision is to revise our Inservice Inspection and Testing Program to:

- (a) Correct errors in the inservice inspection tables.
- (b) Remove size as a factor in examination amount for valves. This is not a requirement of the Code.
- (c) Add inspection of hangers installed during 1978 refueling outage.
- (d) Add testing of instrument line excess flow check valves.

Please contact us if you have any questions related to Revision Number 3 to our Program.

L O Mayer, PE

Manager of Nuclear Support Services

LOM/DMM/deh

cc: J G Keppler

G Charnoff

Attachment

Joseph Japan

February 26, 1979

Revision No. 3 to Monticello ASME Code Section XI Inservice Inspection and Testing Program and Information Required for NRC Review of Requests for Relief from ASME Code Section XI Requirements, dated March 15, 1979

Remove the Following	Insert the Following
Pages from the Manual	Revision No. 2 Pages
ø	,
Title Page	Title Page
iii	iii
1-4	1-4
1-6 thru 1-8	1-6 thru 1-8
1-13 thru 1-16	1-13 thru 1-16
1-21	1-21
1-28	1-28
1-32	1-32
1-33	1-33
1-34	1-34
1-36	1-36
1-40 /	1-40
1-41	1-41 /
1-46	1-46
1-47	1-47
1-47A NOT	- (new page)
3-8 involume to	3-8
3-10	3–10
3-12	3-12
3-20 thru 3-24 NOT IN	- (new pages)
4-8 VOWINE 10	4-8
4-39 Remove	4-39
4-442 NOT IN VOLUME to	- (new page)
4-45 S Remove.	- (new page)
6-1	6-1
6-21 WOT IN VOIUME	- (new page)
to remove -	

Use the "Record of Revisions," page iii, to verify your copy of the program manual is complete and up-to-date following entry of this revision.