

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7912140259 DOC. DATE: 79/12/07 NOTARIZED: NO DOCKET #
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH. NAME: MAYER, L.O. AUTHOR AFFILIATION: Northern States Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION: Office of Nuclear Reactor Regulation

SUBJECT: Confirms 791129 telcon re 791120 response to NRC 791030 ltr concerning lessons learned short term requirements. Requests that exception for Item 2.1.3.6 in Section B of Encl 1 of response be deleted.

DISTRIBUTION CODE: A040S COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Resp to Lesson Learn Task Force - General Electric

NOTES: -----

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	10 BC ORB# 3	7	7			
INTERNAL:	<u>1 REG FILE</u>	1	1	17 I & E	2	2
	19 TA/EDO	1	1	2 NRC PDR	1	1
	20 CORE PERF BR	1	1	21 ENG BR	1	1
	22 REAC SFTY BR	1	1	23 PLANT SYS BR	1	1
	24 EEB	1	1	25 EFLT TRT SYS	1	1
	3 LPDR	1	1	4 NSIC	1	1
	5 D VERRELLI	1	1	6 L. RIANI	1	1
	7 J BEARD	1	1	8 F SKOPEC	1	1
	A REG FILE	1	1	OELD	1	0
EXTERNAL:	10 BC	7	7	26 ACRS	16	16

DEC 18 1979

MA
4

TOTAL NUMBER OF COPIES REQUIRED: LTR 49 ENCL 48

KO

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

December 7, 1979

Director
Office of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Revision to NSP Letter Dated 11/20/79 on
Lessons Learned Supplemental Information

This letter is intended to confirm the telephone discussion between Mr Cecil Thomas of the NRC staff and Messrs W Shamla and M Clarity of the Monticello Plant staff on Thursday, November 29, 1979.

Our November 20, 1979 response to your October 30, 1979 letter concerning Lessons Learned Short Term Requirements stated on page 2 that we intend to meet the implementation schedules contained in Enclosure (2) of Reference (3) (i.e., NRC letter dated October 30, 1979) with the exception of four items. One of these four exceptions, item 2.1.3.b, was inappropriate due to a misunderstanding of the phased approach to guideline implementation and operator training which has been agreed upon by NRR and the GE BWR Owners' Group. We therefore wish to delete the exception for item 2.1.3.b in section B of Enclosure 1 of the November 20, 1979 NSP letter.



L O Mayer, PE
Manager of Nuclear Support Services

LOM/ak

cc: J G Keppler
G Charnoff

7912140

A040

S

1/1

259