DISTRIBUTION	AFTER ISSUAI			116 1010		EGULATORY COM	MISS:	DOCK	ET NUMBER	
C FORM 195 .			7	U.S. NOC	LEMB C		N		50-263	
R)		245	T:E0 DO	CKET M	ATER	ΗΔΙ		FILE	NUMBER	
NRC D	ISTRIBUTION	FOR PAR		CICETIO	1/0.16.			DATE	OF DOCUMENT	
:	NRC		FROM:	Not				12/14/77		
- 11100				Minneapõlis, Minnesota 55401					RECEIVED	
				L. O.					19/77	
						INPUT FORM		NUMB	SER OF COPIES RECEIVED	
LETTER	DNOTORIZE		PROP			INFO! FORM				
☐ ORIGINAL	BUNCLASSI	FIED							100.	
COPY	···			T		1		L		
SCRIPTION	Advising re	equest to	review	a11	ENCLO	20 HE				
	Monticello p	iping fo	or mater	ial						
	susceptible	to stres	s corro	sion						
	cracking and	l a progi	am of a	ugment	ed					
	surveillance	and ins	spection	n will	þе					
	completed for	or submit	tal by	Janura	У					
	31, 1978	•				•				
	•									
	1 n		•							
	1p				İ					
,										
						-				
	MONTICELLO									
PLANT NAME:	jcm 12/23/7	7 <i>;</i>							L.	
•	JCIII 12/23/1	•					40	CC	*5	
			FOR	ACTION	INFOR	MATION				
						MIN 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1				
SAFETY	. /7\	N/		AC: 10.11	T	WATTON				
BRANCH CHIEF	F: (7)	DA	4013	<u> </u>		WATION				
	F: (7)	D1		ACTION		MA11011				
	F: (7)	\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\		<u> </u>						
	7: (7)	DI		ACTION						
	7: (7)	100		ACTION						
	7: (7)	\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	70 IS	ERNAL						
BRANCH CHIEF	7: (7)	100	70 IS							
REG FILE	7: (7)	100	70 IS							
REG FILE	7: (7)	1	70 IS							
REG FILE NRC PDR I & E (2)	7: (7)	1	70 IS							
REG FILE NRC PDR I & E (2) OFLD	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAFR	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAER BUTLER	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAFR BUTLER GRIMES	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAER BUTLER GRIMES U, COLLINS	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK FISENHUT SHAO BAER BUTLER GRIMES	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAER BUTLER GRIMES U, COLLINS	7: (7)		70 IS							
REG FILE NRC POR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAFR BUTLER GRIMES J. COLLINS	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAER BUTLER GRIMES U, COLLINS	7: (7)		70 IS							
REG FILE NRC POR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAER BUTLER GRIMES U, COLLINS	7: (7)		70 IS							
REG FILE NRC POR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAER BUTLER GRIMES U, COLLINS	7: (7)		70 IS							
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAER BUTLER GRIMES U, COLLINS	7: (7)		INT	ERNAL	DISTRI				CONTROL NUMBER	
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK FISENHUT SHAO BAER BUTLER GRIMES J. COLLINS J. MCGOUGH		EXTER	70 IS	ERNAL	DISTRI				CONTROL NUMBER	
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAFR BUTLER GRIMES J. COLLINS J. MCGOUGH			INT	ERNAL	DISTRI				CONTROL NUMBER	
REG FILE NRC PDR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAFR BUTLER GRIMES U. COLLINS U. MCGOUGH		EXTER	INT	ERNAL	DISTRI					
REG FILE NRC POR I & E (2) OFLD HANAUER CHECK EISENHUT SHAO BAER BUTLER GRIMES J. COLLINS J. MCGOUGH LPDR://///		EXTER	INT	RIBUTIO	DISTRI					

NSP

REGULATURY DOCKET FILE COPY

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

December 14, 1977

Director of Nuclear Reactor Regulation U S Nuclear Regulatory Commission Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Augmented Surveillance and Inspection of Piping Susceptible to Stress Corrosion Cracking

In a letter dated September 15, 1977 from Mr D K Davis, Acting Chief, Operating Reactors Branch #2, Division of Operating Reactors, we were requested to review all Monticello piping for material which is susceptible to stress corrosion cracking and submit a program of augmented surveillance and inspection if necessary. We were asked to complete this task within 90 days.

We are now in the process of assembling the information requested in Mr Davis's letter of September 15, 1977. We will be unable to complete this work within the allowed 90 days, however. We believe this work can be completed, including submission of a License Amendment Request with the required proposed Technical Specification changes, by January 31, 1977.

Please contact us if our schedule for complying with Mr Davis's request is not satisfactory.

L.O. Mayer

L O Mayer, PE Manager of Nuclear Support Services

LOM/DMM/deh

cc: J G Keppler

G Charnoff

MPCA

Attn: JW Ferman