

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8012020476 DOC.DATE: 80/11/24 NOTARIZED: NO DOCKET #
 FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH.NAME AUTHOR AFFILIATION
 SHAMLA,W.A. Northern States Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 KEPPLER,J.G. Region 3, Chicago, Office of the Director

SUBJECT: Suppls 801112 ltr re failure of recirculation pump discharge
 bypass valve motor.Event not reportable.Motor failure could
 not have resulted in reduced LPCI flow.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1
 TITLE: Incident Reports

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL		RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	IPPOLITO,T. 04	3			
INTERNAL:	A/D COMP&STRU06	1		A/D ENV TECH 07	1
	A/D MATL & QU08	1		A/D OP REACT009	1
	A/D PLANT SYS10	1		A/D RAD PROT 11	1
	A/D SFTY ASSE12	1		A/D TECHNOLOG13	1
	ACC EVAL BR 14	1		AEOD	2
	ASLBP/J.HARD	1		AUX SYS BR 15	1
	CHEM ENG BR 16	1		CONT SYS BR 17	1
	CORE PERF BR 18	1		D/DIR,HUM FAC19	1
	DIR,ENGINEERI20	1		DIR,HUM FAC S21	1
	DIR,SYS INTEG22	1		EFF TR SYS BR23	1
	EQUIP QUAL BR25	1		GEOSCIENCES 26	1
	I&C SYS BR 29	1		I&E 05	2
	JORDAN,E./IE	1		LIC GUID BR 30	1
	LIC QUAL BR 31	1		MATL ENG BR 32	1
	MECH ENG BR 33	1		MPA	3
	NRC PDR 02	1		OP EX EVAL BR34	3
	OR ASSESS BR 35	1		POWER SYS BR 36	1
	RAD ASSESS BR39	1		REACT SYS BR 40	1
	<u>REG FILE</u> 01	1		REL & RISK A 41	1
	SFTY PROG EVA42	1		STRUCT ENG BR44	1
	SYS INTERAC B45	1			
EXTERNAL:	ACRS 46	16	16	LPDR 03	1
	NSIC 05	1	1	TERA:DOUG MAY	1

TOTAL NUMBER OF COPIES REQUIRED: LTR 69 ENCL 0

NSP

NORTHERN STATES POWER COMPANY

Monticello Nuclear Generating Plant
P. O. Box 600
Monticello, Minnesota 55362

US NRC
DISTRIBUTION SERVICES
BRANCH

180 DEC 1 AM 11 46

US NRC
DISTRIBUTION SERVICES
BRANCH

November 24, 1980

Mr. J. G. Keppler, Director
Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137


Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Reference: Letter from W. A. Shamla to J. G. Keppler dated November 12, 1980, Concerning the Failure of a Recirc Pump Discharge Bypass Valve Motor.

Further investigation revealed that the motor failure could not have resulted in reduced LPCI flow. Therefore, this event is not considered reportable.

Yours very truly,



W. A. Shamla
Plant Manager

WAS/djw

cc: Director, Office of Management
Information and Program Control File

A002
S/10

P

8012020476