

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8103300149 DOC. DATE: 81/03/24 NOTARIZED: NO DOCKET #
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH. NAME AUTHOR AFFILIATION
 MAYER, L.O. Northern States Power Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Office of Nuclear Reactor Regulation, Director

SUBJECT: Forwards NEDE-20179-4P, Suppl 4, "Monticello Nuclear
 Generating Plant, Unit 1, SRP-II Bundle Submittal Segmented
 Test Rod Bundle." Encl withheld (ref 10CFR2.790). *566 sub file*

DISTRIBUTION CODE: PA01S COPIES RECEIVED: LTR 5 ENCL 5 SIZE: 1+8
 TITLE: Proprietary Review Distribution - OL Stage

NOTES:

ACTION:	RECIPIENT		COPIES		RECIPIENT	COPIES		
	ID CODE/NAME		LTTR	ENCL		ID CODE/NAME	LTTR	ENCL
	IPPOLITO, T.	<i>#5-11</i>	7	7	ECCLESTAN, K.	<i>#2</i>	1	1
INTERNAL:	I&E	<i>#3,4</i>	09	2	2	NRC PDR	1	0
	OELD			1	0	REG FILE #1	1	1
EXTERNAL:	ACRS	<i>12-27</i>	19	16	16	LPDR	1	0
	NSIC			1	0			

VP

TOTAL NUMBER OF COPIES REQUIRED: LTR 31 ENCL 27

APR

NSP

NORTHERN STATES POWER COMPANY


MINNEAPOLIS, MINNESOTA 55401

March 24, 1981

Director of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Change to NEDE-20179
Monticello Segmented Test Rod Bundle
(Proprietary Information)



On December 14, 1973, we submitted proprietary report NEDE-20179 describing the Monticello Segmented Test Rod Bundle. Revisions to that report were subsequently submitted to the U S Nuclear Regulatory Commission on January 15, 1974; August 20, 1975; July 18, 1977; August 23, 1978; and October 5, 1979. Each of these submittals were provided to document the changes made to the Segmented Test Rod Bundle within the scope of the initially described program.

During our Spring, 1981 refueling outage, we intend to make other similar changes. We are, therefore, submitting five copies of NEDE-20179-4P, Supplement 4, to maintain your files in a current status. The changes are being reviewed, documented and reported in accordance with 10CFR50.59.

Subsequent to the October 5, 1979 submittal of changes, minor revisions to the number of replacement segments were proposed and reviewed prior to the 1980 refueling outage. The changes were documented in the Monticello Annual Operating Report submitted to the U S Nuclear Regulatory Commission on February 27, 1981, but since that is a non-proprietary submittal, replacement pages for NEDE-20179 were not included. To maintain your files in a current status, we have also included five copies of the December 26, 1979 revision pages for NEDE-20179-3P.

All necessary information for establishing the proprietary nature of this information was included with the December 14, 1973 submittal; therefore, we request limited distribution of the attached documents consistent with proprietary information procedures.

L.O. Mayer

L O Mayer, PE
Manager of Nuclear Support Services

LOM/bd

cc: J G Keppler (w/o proprietary information)
NRC Resident Inspector " " "
G Charnoff


PA01
S 5/5

8103300 149

ATTACHMENT CONTAINS 10 CFR PART 2.790(a)(4) INFORMATION

P

30



1954
11/15
11/15
11/15
11/15

DOCKET NO. 50-263

DATE: 3/31/81

NOTE TO NRC AND/OR LOCAL PUBLIC DOCUMENT ROOMS

The following item submitted with letter dated 3/24/81
from Northern States Pwr Co. is being withheld from public disclosure
in accordance with Section 2.790.

PROPRIETARY INFORMATION

FORWARD NEDE-20179-4P Suppl. #4

Sharon Hunt
m/s 016

Distribution Services Branch

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

March 24, 1981

Director of Nuclear Reactor Regulation
U S Nuclear Regulatory Commission
Washington, DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Change to NEDE-20179
Monticello Segmented Test Rod Bundle
(Proprietary Information)

On December 14, 1973, we submitted proprietary report NEDE-20179 describing the Monticello Segmented Test Rod Bundle. Revisions to that report were subsequently submitted to the U S Nuclear Regulatory Commission on January 15, 1974; August 20, 1975; July 18, 1977; August 23, 1978; and October 5, 1979. Each of these submittals were provided to document the changes made to the Segmented Test Rod Bundle within the scope of the initially described program.

During our Spring, 1981 refueling outage, we intend to make other similar changes. We are, therefore, submitting five copies of NEDE-20179-4P, Supplement 4, to maintain your files in a current status. The changes are being reviewed, documented and reported in accordance with 10CFR50.59.

Subsequent to the October 5, 1979 submittal of changes, minor revisions to the number of replacement segments were proposed and reviewed prior to the 1980 refueling outage. The changes were documented in the Monticello Annual Operating Report submitted to the U S Nuclear Regulatory Commission on February 27, 1981, but since that is a non-proprietary submittal, replacement pages for NEDE-20179 were not included. To maintain your files in a current status, we have also included five copies of the December 26, 1979 revision pages for NEDE-20179-3P.

All necessary information for establishing the proprietary nature of this information was included with the December 14, 1973 submittal; therefore, we request limited distribution of the attached documents consistent with proprietary information procedures.



L O Mayer, PE
Manager of Nuclear Support Services

LOM/bd

cc: J G Keppler (w/o proprietary information)
NRC Resident Inspector " " "
G Charnoff