



Northern States Power Company

Monticello Nuclear Generating Plant P.O. Box 600 Monticello, Minnesota 55362

April 10, 1985

Mr. J. G. Keppler
Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-264 License No. DPR-22

The following is in response to Item 5 of IE Bulletin 83-03 titled "Check Valve Failures in Raw Water Cooling Systems of Diesel Generators". Item 5 requires that licensees report the results of the initial valve integrity verification. In a letter dated June 3, 1983, from C.E. Larson to Director, Office of Inspection and Enforcement, a list of ten (10) valves governed by IEB 83-03 was given. Initial integrity verification of these valves was completed on January 15, 1985. No failures were found. This fulfills the requirements of IE Bulletin 83-03.

It is estimated that 2000 manhours were required to implement IE Bulletin 83-03. This estimate includes engineering time (i.e., written responses, seismic analysis, piping study) and construction labor.

Respectfully,

C. E. Larson

V. P., Nuclear Generation

CEL/jma

c: NRC Resident Inspector G Charnoff

> 8504260004 850410 PDR ADOCK 05000263 PDR

> > JE 10 APR 18 1985