NSP

Me. H- Hote Data Skeed attached

NODTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

July 23, 1980

Little adequate ?

Mr. R. V. Heishman, Chief
Reactor Operations and Nuclear
Support Branch
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Dear Mr. Heishman:

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

The following is offered in response to IE Inspection Report No. 80-12:

1. Corrective Action

The Licensed Operator Requalification Program at the Monticello Nuclear Generating Plant has been revised to incorporate the procedure for the Training Department to use in notifying the operations group of licensed personnel who are required to attend accelerated retraining. The revised requalification program will be submitted to the Operator License Branch prior to August 1, 1980. The program will also contain requirements set forth in Mr. Denton's March 28, 1980 letter.

2. Avoiding Further Non-Compliance

By the use of the above mentioned procedure, further non-compliance in this area will be avoided.

3. Full Compliance

Full compliance is presently in effect.

Yours truly,

D. E. Gilberts

Vice President

Power Production

cc: Mr. G. Charnoff

DEG:nk

JUL 28 1980