



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401-1927
Telephone (612) 330-5500

February 21, 1992

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

10 CFR Part 50
Section 50.54(f)

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22


Response to Systematic Assessment of Licensee
Performance (SALP) Inspection Report No 50-263/91001

Reference: Letter dated February 7, 1992 from A Bert Davis, Regional Administrator, Region III, NRC, to L R Eliason with Initial SALP 10 Board Report, Inspection Report No. 50-263/91001.

Your letter dated February 7, 1992 solicited written comments related to the Systematic Assessment of Licensee Performance (SALP) Board Initial Report covering the period July 1, 1990, through November 30, 1991 (SALP 10).

The SALP 10 Report was the subject of a public meeting held at the Monticello Training Center on February 20, 1992. We have no additional comments to offer related to the SALP 10 Report.

As we noted at the February 20, 1992 meeting, we appreciate the feedback the SALP process provides related to the operation of our nuclear generating plants. The analysis provided in the SALP 10 Report will be used to strengthen those areas where weaknesses are evident and provide further improvements in those areas in which we performed strongly.


Leon R. Eliason
Vice President
Nuclear Generation

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
MDH, Attn: Dr R Thron
J Silberg

9202250324