

**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  Mistras Group, Inc. 161 Tower Drive, Suite E Burr Ridge, IL  REPORT NUMBER(S) 2011-04	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S)  030-35114	4. LICENSE NUMBER(S)  12-16559-02	5. DATE(S) OF INSPECTION  10/24/11, with in-office review through 11/14/11
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED  87121	7. INSPECTION FOCUS AREAS  02.04, 02.06, and 02.07
--	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  03320	2. PRIORITY  1	3. LICENSEE CONTACT  Daryl Istre, RSO	4. TELEPHONE NUMBER  (713) 899-4338
---------------------------------	----------------------	---	---

Main Office Inspection      Next Inspection Date: 10/24/2012

Field Office Inspection

Temporary Job Site Inspection

**PROGRAM SCOPE**

The in-office review included receipt and review of information that was unavailable during the on site inspection, including information regarding an annual audit record. The Burr Ridge, Illinois facility is not the licensee's corporate office. The licensee's corporate office is at 195 Clarksville Road, Princeton Junction, New Jersey. The telephone number of the corporate office is 609-716-4157. This inspection was essentially limited to interviews with the licensee's Director of Regulatory Affairs and other staff members, and review of selected records. The Burr Ridge, Illinois facility was open from 7:30 am to 4:30 pm Monday through Friday. The RSO, who was stationed in Texas, reported to the Director of Regulatory Affairs, who was stationed in Burr Ridge, Illinois. Most of the documents required by 10 CFR Part 34 were located at the locations of use.

The inspectors observed: (1) records indicating that selected radiography staff members were technically qualified; (2) leak test records of selected sealed sources in NRC jurisdiction; (3) records of 6 month radiography staff audits; and (4) the 2010 Radiation Protection Program Audit records for the Hobart and Edwardsport facilities.