

## Comment Resolution Summary

### Resolution of Comments for IP 90003 CONSTRUCTION MULTIPLE/ REPETITIVE DEGRADED CORNERSTONE COLUMN INSPECTIONS

Source	Comment	Added	Remarks
RI	Section 02.03e3 Instead of referring to procedure and documentation meets the requirements specified in IP 35007 Appendix 10, 11 and 14 provide the list requirements in this section or put these requirements in under the guidance Section 03.03e.	Y	
RI	Section 02.03e6 Delete - until the 52.103(g) Commission finding	Y	
RI	Section 02.08 NRC Assessment Delete this entire section as it has nothing to do with the inspection. This should either be dropped or added under guidance Section 03.08.	N	While not directly related to an inspectable area, it remains a significant requirement as a means of determining NRC program effectiveness at assessing the licensee in the fourth column.
RI	01.01 To provide ... are necessary to (delete "arrest", add "change and correct") declining performance.	Y	
RI	Page 17, grammar (2) Does (replace with "Do") the changes invalidate ...	Y	
RG II	No Comments		
RG III	No Comments		
RG IV	No Comments		