




DEC-08-2011 12:48

USNRC R1 LAS

P.002

NRC FORM 591M PART 1 <small>(10-2010)* 10 CFR 2.201</small>		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Naugatuck Valley Radiological Associates 385 Main Street South Southbury, Connecticut 06488		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT Nos 2011-001			
3. DOCKET NUMBER(S) 030-34024	4. LICENSE NUMBER(S) 06-30265-01	5. DATE(S) OF INSPECTION December 2, 2011	
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the Inspector. The inspection findings are as follows:			
<input type="checkbox"/> 1. Based on the inspection findings, no violations were identified.			
<input type="checkbox"/> 2. Previous violation(s) closed.			
<input checked="" type="checkbox"/> 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.			
<p style="margin-left: 40px;">X Non-Cited Violation was discussed involving the following requirement and Corrective Action:</p> <p style="margin-left: 40px;">10 CFR 35.13(f) requires, in part, that a licensee apply for and receive a license amendment before it changes the address of use identified on the license. Contrary to the above, on December 1, 2011, the licensee did not apply for or receive a license amendment before it changed the address of use identified on the license. Specifically, on December 1, 2011, the licensee transported multiple calibration sealed sources (Co-57, Ba-133, and Cs-137) to a location of use that was not specified on the license.</p> <p style="margin-left: 40px;">Corrective actions included the licensee requesting an expedited license amendment to add the new location of use to the license. The amendment was issued on December 2, 2011.</p>			
<input type="checkbox"/> 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.			
Statement of Corrective Actions			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.			
Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Beth Ouellette		12/8/11
NRC INSPECTOR	Tara L. Weidner		12/6/2011
BRANCH CHIEF	JOSEPH NICK Joseph Nick		12/15/11

*591M PART 1 (RI Rev. 08/10/2011)

G:\WordDocs\Current\Insp Record\RO6-30265-01.2011-001.591M-Part1.doc

SUNSI Review Completed By:

/ RA / TLWeidner

Public
 Non-Sensitive

This document becomes an NRC Official Agency Record once it is signed by the Branch Chief