

L-3

06-30610-01  
03035611

Attention:  
Laurie A. Kauffman  
Leak Test

LEAK TEST CERTIFICATE

Wipe Date 10/3/11

Instructions

- 1 Use wipe procedures as described in the device manual.
- 2 Enter all information under description.
- 3 Print or type return address in the space provided.
- 4 Wipe source (s) and put filter paper in the plastic bag.
- 5 Keep the middle copy and mail this form and bag to Humboldt.
- 6 Regulations require that sources with removable activity greater than 0.005 uCi be removed from service for repair and decontamination or disposal. Authorities must be notified.

DESCRIPTION OF DEVICE/SOURCE

Model C-300 Ser 21011

SOURCE 1 SOURCE 2

Material CS 137 Am 241:Be

Source Ser .3 GBq 1.48 GBq

RSO Name Phil Pelilla

Telephone (203) 996-8800

Do Not Write In This Space  
For HSI Use Only

REMOVABLE ACTIVITY

Beta/Gamma 0 Alpha 0

0 uCi 0 uCi

Humboldt Scientific

By DOTV

Date 10/10/11

5200174  
Return  
Address  
Label  
Please  
Type or  
Print  
Clearly

- Q/C Resource Technical Services  
- 3 Simm Lane  
- Newtown, CT 06470

HUMBOLDT SCIENTIFIC INC. 551D Pylon Drive, Raleigh, NC 27606, (919) 832-6509

REC'D IN LAT 1/30/12

576646  
NMSS/RGN1 MATERIALS-002