

Part 21 (PAR)

Event # 47643

Rep Org: CURTISS WRIGHT FLOW CONTROL CO.		Notification Date / Time: 02/06/2012 17:56 (EST)	
Supplier: CURTISS WRIGHT FLOW CONTROL CO.		Event Date / Time: 02/06/2012 (CST)	
Last Modification: 02/06/2012			
Region: 1	Docket #:		
City: HUNTSVILLE	Agreement State: Yes		
County:	License #:		
State: AL			
NRC Notified by: TONY GILL		Notifications: JONATHAN BARTLEY	
HQ Ops Officer: CHARLES TEAL		PART 21 GROUP	
Emergency Class: NON EMERGENCY		R2DO	
10 CFR Section:		EMAIL	
21.21	UNSPECIFIED PARAGRAPH		

PART 21 - DEFECTIVE PLUG INSULATORS

The following report was received via fax:

"This letter is issued to provide initial notification of a potential defect in Plug Insulators (P/N: GB-1A-1) supplied as part of GRAYBOOT 'A' (GB-1A) Connector Kits. There are two affected lots of Plug Insulators (Lot #: BA59961 and BA67711). The potential defect is an out of tolerance dimension that will possibly affect the sealing ability of the Plug Insulator to wire interface.

"The affected Customers and their associated Purchase Orders are listed below. All Customers will be notified today.

- Ralph a. Hiller; PO: NUC7505, Item 1, 15 Kits (P/N: GB-1A [16-18], Lot BA59961) supplied 19JAN2012.
- Bruce Power, PO: 00168187, Item 1, 20 Kits (P/N: GB-1A [12-14], Lot BA59961) supplied 13DEC2011.
- Dominion - Surry, PO: 45886290, Item 1, 22 Kits (P/N: GB-S-1A, Lot BA59961) supplied 19DEC2011.
- Dominion - Surry, PO: 45897749, Item 2, 30 Kits (P/N: GB-S-1A, Lot BA67711) supplied 01FEB2012.
- Ringhals AB, PO: 621728-053, Item 10, 30 Kits (P/N: GB-1A [16-18], Lot BA59961) supplied 19DEC2011.
- Ringhals, PO: 620625-066, Item 10, 300 parts (P/N: GB-1A-1, Lots BA59961/BA67711) supplied 30JAN2012.
- Ringhals, PO: 620996-066, Item 50, 1 Kit (P/N: GB-1A [16-18], Lot BA59961) supplied 29NOV2011.
- OKG, PO: 4113847, Item 4, 86 parts (P/N: GB-1A-1, Lot BA59961) supplied 30NOV2011.

"It is requested that all affected parts be returned for replacement to QualTech NP; 330 West Park Loop; Huntsville, AL 35806. Customers can contact Cindy Tidwell at (256) 895-7250 ext. 229 for freight collect shipping instructions.

IEI9
NRR

Part 21 (PAR)

Event # 47643

"Additional details, corrective actions and root causes will be provided once complete. If you require additional information or would like to discuss this further please do not hesitate in contacting:"

Tony Gill
Quality Assurance Supervisor
QualTech NP, Huntsville
A business unit of Curtiss-Wright Flow Control Company
Office 256-722-8500 ext. 1
Cell 256-426-4558
tgill@curtisswright.com



QualTech NP
125 West Park Loop
Huntsville, AL 35806
Phone: 256.722.8500 • Fax: 256.722.8533
www.qualtechnp.com

FAX TRANSMITTAL

DATE: 2-6-12

TO: US NRC

FAX NO: 301-816-5151

FROM: Tony Gill 256-426-4558

COMMENTS/INSTRUCTIONS: _____

Attach please find the
notification letter concerning
a potential defect under
LOCFR21.

Sincerely,
Tony Gill

TRANSMITTAL INCLUDES COVER SHEET PLUS 1 PAGE(S).



Huntsville Operations
125 & 330 West Park Loop
Huntsville, AL 35806
256-722-8500

(File No.: QTHuntsville10CFR21-2012-01)

February 06, 2012

To whom it may concern:

This letter is issued to provide initial notification of a potential defect in Plug Insulators (P/N: GB-1A-1) supplied as part of GRAYBOOT "A" (GB-1A) Connector Kits. There are two affected lots of Plug Insulators (Lot #: BA59961 and BA67711). The potential defect is an out of tolerance dimension that will possibly affect the sealing ability of the Plug Insulator to wire interface.


The affected Customers and their associated Purchase Orders are listed below. All Customers will be notified today.

Ralph a. Hiller; PO: NUC7505, Item 1, 15 Kits (P/N: GB-1A [16-18], Lot BA59961) supplied 19JAN2012.
Bruce Power, PO: 00168187, Item 1, 20 Kits (P/N: GB-1A [12-14], Lot BA59961) supplied 13DEC2011.
Dominion - Surry, PO: 45886290, Item 1, 22 Kits (P/N: GB-S-1A, Lot BA59961) supplied 19DEC2011.
Dominion - Surry, PO: 45897749, Item 2, 30 Kits (P/N: GB-S-1A, Lot BA67711) supplied 01FEB2012.
Ringhals AB, PO: 621728-053, Item 10, 30 Kits (P/N: GB-1A [16-18], Lot BA59961) supplied 19DEC2011.
Ringhals, PO: 620625-066, Item 10, 300 parts (P/N: GB-1A-1, Lots BA59961/BA67711) supplied 30JAN2012.
Ringhals, PO: 620996-066, Item 50, 1 Kit (P/N: GB-1A [16-18], Lot BA59961) supplied 29NOV2011.
OKG, PO: 4113847, Item 4, 86 parts (P/N: GB-1A-1, Lot BA59961) supplied 30NOV2011.

It is requested that all affected parts be returned for replacement to QualTech NP; 330 West Park Loop; Huntsville, AL 35806. Customers can contact Cindy Tidwell at (256) 895-7250 ext. 229 for freight collect shipping instructions.

Additional details, corrective actions and root causes will be provided once complete. If you require additional information or would like to discuss this further please do not hesitate in contacting me.

Sincerely,



Tony Gill
Quality Assurance Supervisor
QualTech NP, Huntsville
a business unit of Curtiss-Wright Flow Control Company
Office 256-722-8500 ext. 131
Cell 256-426-4558
tgill@curtisswright.com