

Part 21 (PAR)

Event # 47643

<b>Rep Org:</b> CURTISS WRIGHT FLOW CONTROL CO.	<b>Notification Date / Time:</b> 02/06/2012 17:56 (EST)
<b>Supplier:</b> CURTISS WRIGHT FLOW CONTROL CO.	<b>Event Date / Time:</b> 02/06/2012 (CST)
	<b>Last Modification:</b> 02/06/2012
<b>Region:</b> 1	<b>Docket #:</b>
<b>City:</b> HUNTSVILLE	<b>Agreement State:</b> Yes
<b>County:</b>	<b>License #:</b>
<b>State:</b> AL	
<b>NRC Notified by:</b> TONY GILL	<b>Notifications:</b> JONATHAN BARTLEY R2DO
<b>HQ Ops Officer:</b> CHARLES TEAL	PART 21 GROUP EMAIL
<b>Emergency Class:</b> NON EMERGENCY	
<b>10 CFR Section:</b>	
21.21 UNSPECIFIED PARAGRAPH	

PART 21 - DEFECTIVE PLUG INSULATORS

The following report was received via fax:

"This letter is issued to provide initial notification of a potential defect in Plug Insulators (P/N: GB-1A-1) supplied as part of GRAYBOOT 'A' (GB-1A) Connector Kits. There are two affected lots of Plug Insulators (Lot #: BA59961 and BA67711). The potential defect is an out of tolerance dimension that will possibly affect the sealing ability of the Plug Insulator to wire interface.

"The affected Customers and their associated Purchase Orders are listed below. All Customers will be notified today.

- Ralph a. Hiller; PO: NUC7505, Item 1, 15 Kits (P/N: GB-1A [16-18], Lot BA59961) supplied 19JAN2012.
- Bruce Power, PO: 00168187, Item 1, 20 Kits (P/N: GB-1A [12-14], Lot BA59961) supplied 13DEC2011.
- Dominion - Surry, PO: 45886290, Item 1, 22 Kits (P/N: GB-S-1A, Lot BA59961) supplied 19DEC2011.
- Dominion - Surry, PO: 45897749, Item 2, 30 Kits (P/N: GB-S-1A, Lot BA67711) supplied 01FEB2012.
- Ringhals AB, PO: 621728-053, Item 10, 30 Kits (P/N: GB-1A [16-18], Lot BA59961) supplied 19DEC2011.
- Ringhals, PO: 620625-066, Item 10, 300 parts (P/N: GB-1A-1, Lots BA59961/BA67711) supplied 30JAN2012.
- Ringhals, PO: 620996-066, Item 50, 1 Kit (P/N: GB-1A [16-18], Lot BA59961) supplied 29NOV2011.
- OKG, PO: 4113847, Item 4, 86 parts (P/N: GB-1A-1, Lot BA59961) supplied 30NOV2011.

"It is requested that all affected parts be returned for replacement to QualTech NP; 330 West Park Loop; Huntsville, AL 35806. Customers can contact Cindy Tidwell at (256) 895-7250 ext. 229 for freight collect shipping instructions.

IEI9  
NRR

Part 21 (PAR)

Event # 47643

"Additional details, corrective actions and root causes will be provided once complete. If you require additional information or would like to discuss this further please do not hesitate in contacting:"

Tony Gill  
Quality Assurance Supervisor  
QualTech NP, Huntsville  
A business unit of Curtiss-Wright Flow Control Company  
Office 256-722-8500 ext. 1  
Cell 256-426-4558  
tgill@curtisswright.com

\*\*\*\*\*



QualTech NP  
125 West Park Loop  
Huntsville, AL 35806  
Phone: 256.722.8500 • Fax: 256.722.8533  
www.qualtechnp.com

**FAX TRANSMITTAL**

DATE: 2-6-12

TO: US NRC

FAX NO: 301-816-5151

FROM: Tony Gill 256-426-4558

COMMENTS/INSTRUCTIONS: \_\_\_\_\_

Attach please find the  
notification letter concerning  
a potential defect under  
LOCFR21.

Sincerely,  
Tony Gill

TRANSMITTAL INCLUDES COVER SHEET PLUS 1 PAGE(S).



Huntsville Operations  
125 & 330 West Park Loop  
Huntsville, AL 35806  
256-722-8500

(File No.: QTHuntsville10CFR21-2012-01)

February 06, 2012

To whom it may concern:

This letter is issued to provide initial notification of a potential defect in Plug Insulators (P/N: GB-1A-1) supplied as part of GRAYBOOT "A" (GB-1A) Connector Kits. There are two affected lots of Plug Insulators (Lot #: BA59961 and BA67711). The potential defect is an out of tolerance dimension that will possibly affect the sealing ability of the Plug Insulator to wire interface.


The affected Customers and their associated Purchase Orders are listed below. All Customers will be notified today.

Ralph a. Hiller; PO: NUC7505, Item 1, 15 Kits (P/N: GB-1A [16-18], Lot BA59961) supplied 19JAN2012.  
Bruce Power, PO: 00168187, Item 1, 20 Kits (P/N: GB-1A [12-14], Lot BA59961) supplied 13DEC2011.  
Dominion - Surry, PO: 45886290, Item 1, 22 Kits (P/N: GB-S-1A, Lot BA59961) supplied 19DEC2011.  
Dominion - Surry, PO: 45897749, Item 2, 30 Kits (P/N: GB-S-1A, Lot BA67711) supplied 01FEB2012.  
Ringhals AB, PO: 621728-053, Item 10, 30 Kits (P/N: GB-1A [16-18], Lot BA59961) supplied 19DEC2011.  
Ringhals, PO: 620625-066, Item 10, 300 parts (P/N: GB-1A-1, Lots BA59961/BA67711) supplied 30JAN2012.  
Ringhals, PO: 620996-066, Item 50, 1 Kit (P/N: GB-1A [16-18], Lot BA59961) supplied 29NOV2011.  
OKG, PO: 4113847, Item 4, 86 parts (P/N: GB-1A-1, Lot BA59961) supplied 30NOV2011.

It is requested that all affected parts be returned for replacement to QualTech NP; 330 West Park Loop; Huntsville, AL 35806. Customers can contact Cindy Tidwell at (256) 895-7250 ext. 229 for freight collect shipping instructions.

Additional details, corrective actions and root causes will be provided once complete. If you require additional information or would like to discuss this further please do not hesitate in contacting me.

Sincerely,



Tony Gill  
Quality Assurance Supervisor  
QualTech NP, Huntsville  
a business unit of Curtiss-Wright Flow Control Company  
Office 256-722-8500 ext. 131  
Cell 256-426-4558  
tgill@curtisswright.com