

Boyle, Patrick

109/108

From: Martin, Robert *MR*
Sent: Monday, September 12, 2011 11:13 AM
To: Boyle, Patrick
Subject: RE: observation at North Anna similar to KK event

Suggest sharing w Greg, the SRI. I'm so inundated with other stuff, I don't have time to absorb it.

-----Original Message-----
From: Boyle, Patrick *MR*
Sent: Monday, September 12, 2011 9:26 AM
To: Martin, Robert
Subject: observation at North Anna similar to KK event

Bob,

This is an interesting observation in light of the KK event.

Common: - Licensee has identified some damage to porcelain insulators on 500kV current transformer in switchyard. Evaluation in progress, path forward may affect U2 RFO schedule based on maintaining offsite power reliability. - Systems walk downs U1 - 99%, U2 - 100% complete - Structural walk downs 98% complete

Unit 1: - Yellow for Containment Closure - 'A' and 'C' RCS loops isolated and drained to support forced outage activities

Unit 2: - Yellow for Containment Closure - Mode 6 OD approved by facility safety review committee on 9/9. - 'A' and 'C' RCS loops isolated and drained - Schedule shows licensee continuing RFO activities with reactor disassembly continuing, potential head lift on Tuesday 9/13 based on current transformer issue discussed above.

Patrick

~~D~~
108