

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 02/29/2012)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME5167	RIS 'Staff Position on the Clarification of Submitting of Alter. Under 10 CFR 50.55'	O	15.0	12/13/2010	DCI
ME5784	RIS 'Selecting Edition and Addenda of Section XI of ASME Code for Part 52 Inspection Programs'	O	12.0	03/07/2011	NRO
ME6641	RIS 'Clarification of Methods For Applicant And Vendor Compliance With Part 21'	O	8.0	07/05/2011	NMSS
ME6862	RIS 'Endorsement of NEI Guidance Addendum for Managing Personnel Fatigue at Power Reactor Sites'	O	7.0	08/15/2011	DIRS
ME7133	RIS 'Reintegration of Security into the Reactor Oversight Process Action Matrix'	O	6.0	09/19/2011	DIRS
ME7208	RIS 'Use of 10 CFR 72.212 Evaluations to Accept Conditions Outside of the FSAR Analysis	O	6.0	09/29/2011	NMSS
ME7895	RIS '10 CFR Part 21 Evaluation and Reporting Requirements'	O	2.0	01/27/2012	DIRS
ME7896	RIS 'Content Specification and Shielding Evaluations for Type B Packages'	O	2.0	01/27/2012	NMSS
ME4076	IN 'Non-Conservatisms with Spent Fuel Pool Criticality Analyses'	O	21.0	06/16/2010	DPR
ME6847	IN 'Hydrology Study Affects Design Basis External Flooding Evaluation'	O	7.0	08/12/2011	DE
ME7139	IN 'Electrolytic Capacitor Degradation Issues'	O	6.0	09/19/2011	DIRS
ME7178	IN 'Plant Systems that have Leaked with the Potential for Groundwater Contamination'	O	6.0	09/26/2011	DPR

**Open Generic Communication TACs (PA No. 115126CA/B)
Summary Report (AS OF 02/29/2012)**

TAC NO.	TAC TITLE	STATUS	AGE (Mon)	TAC OPENED	LEAD ORG
ME7565	IN 'Fuel Assembly Design Evaluation for a Seismic Event'	O	4.0	11/15/2011	NRO
ME7680	IN 'Preconditioning of Pressure Switches Surveillance Testing'	O	3.0	12/09/2011	EICB
ME7681	IN 'Ineffective Use of Vendor Technical Recommendations'	O	3.0	12/09/2011	IOEB
ME7682	IN 'Hazardous Chemical Fumes Impact Plant Operations'	O	3.0	12/09/2011	IOEB
ME7683	IN 'Ventilation System Design Control Issues Challenge Safety System Function'	O	3.0	12/09/2011	IOEB
ME7769	IN 'Effluent Monitoring and Control Program at Nuclear Power Plants'	O	2.0	01/04/2012	DRA
ME7921	IN 'Tube-to-Tube Contact and Resultant Wearing of the Tubes in Steam Generators'	O	1.0	02/06/2012	DE
ME7941	IN 'Motor-Operated Valve Inoperable Due To Stem-Disc Separation'	O	1.0	02/09/2012	DE
ME7973	IN 'Design Vulnerability in Electrical Power System'	O	1.0	02/15/2012	DE
ME5720	GL 'Implications of Updated Probabilistic Seismic Hazard Estimates in Central and Eastern US of Existing Plants'	O	13.0	02/22/2011	DPR