

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:
Innovative Technical Solutions, Inc.
2730 Shadelands Drive, Suite 100
Walnut Creek California 94598
Locations: 2730 Shadelands Dr., Suite 100, Walnut Creek, CA
& Hunters Point Naval Shipyard, San Francisco, CA

2. NRC/REGIONAL OFFICE

U.S. Nuclear Regulatory Commission
Region IV, 1600 East Lamar Boulevard
Arlington, Texas 76011-4511

REPORT NO: 030-38058/2012-001

3. DOCKET NUMBER
030-38058

4. LICENSE NUMBER
04-29353-01

5. DATE OF INSPECTION
February 07, 2012



LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
 - Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| Title | Printed Name | Signature | Date |
|---------------------------|--------------------|--|------------|
| LICENSEE'S REPRESENTATIVE | | | |
| NRC INSPECTOR | R. Rick Muñoz |  | 02/27/2012 |
| BRANCH CHIEF | G. Michael Vasquez |  | 3/9/12 |

Munoz, Rick

From: Munoz, Rick
Sent: Tuesday, February 28, 2012 7:04 AM
To: JPride@itsi.com
Cc: Munoz, Rick
Subject: NRC Inspection
Attachments: SCAN4672_000.pdf

Mr. Pride,

The NRC has completed additional in-office review of records pertaining to a routine inspection of your NRC license. I am sending you a scanned pdf file of a clear NRC Form 591M inspection report which documents the inspection of Innovative Technology Solutions Inc., at your offices in Walnut Creek and activities at Hunters Point, California, which was conducted on on February 7, 2012. A special thanks to Kent Baugh, Project Manager and Arvin Acharia, Project Manager, for assisting me in obtaining records and providing contact numbers for essential personnel during the NRC site visit. If you have any questions about the inspection or the 591 please call me at (817) 220-1220

Please note: new address & telephone number.

Kindest Regards,

Rick Muñoz
Nuclear Materials Inspector
NRC Region-IV
1600 East Lamar Boulevard
Arlington, TX 76011-4511

Office: (817) 200-1220
Cell: (512) 773-8520
Fax: (817) 200-1188



The information contained in this message may be privileged and/or confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please notify the sender immediately by replying to the message and deleting the material from any computer.

Note: Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of the Nuclear Regulatory Commission, Region-IV or the Nuclear Materials Safety Branch-A. All e-mails are subject to monitoring and archival.

Finally, the recipient should check this message and any attachments for the presence of viruses. The Nuclear Regulatory Commission accepts no liability for any damage caused by any virus transmitted by this e-mail.