

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Fluke Electronics Corporation
6045 Cochran Road
Solon, OH 44139

REPORT NUMBER(S) 12-01

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-30726

4. LICENSE NUMBER(S)

34-25957-03E

5. DATE(S) OF INSPECTION

April 5, 2012

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:



- ☒ 1. Based on the inspection findings, no violations were identified.
- ☐ 2. Previous violation(s) closed.
- ☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- ☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| TITLE | PRINTED NAME | SIGNATURE | DATE |
|---------------------------|-------------------|--|---------|
| LICENSEE'S REPRESENTATIVE | | | |
| NRC INSPECTOR | Robert P. Hays |  | 4/5/12 |
| BRANCH CHIEF | Tamara E. Bloomer |  | 4/12/12 |

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| | | | |
|--|--|---|--|
| 1. LICENSEE/LOCATION INSPECTED: Fluke Electronics Corporation 6045 Cochran Road Solon, OH 44139 REPORT NUMBER(S) 12-01 | | 2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352 | |
| 3. DOCKET NUMBER(S) 030-30726 | 4. LICENSE NUMBER(S) 34-25957-03E | 5. DATE(S) OF INSPECTION April 5, 2012 | |
| 6. INSPECTION PROCEDURES USED 87126 | 7. INSPECTION FOCUS AREAS 03.01-03.07 | | |

SUPPLEMENTAL INSPECTION INFORMATION

| | | | |
|--|----------------------|--|---|
| 1. PROGRAM CODE(S) 03251 | 2. PRIORITY 5 | 3. LICENSEE CONTACT Mark Svajger, RSO | 4. TELEPHONE NUMBER (440) 248-9300 |
| <input checked="" type="checkbox"/> Main Office Inspection Next Inspection Date: 04/05/2017 <input type="checkbox"/> Field Office Inspection <input type="checkbox"/> Temporary Job Site Inspection | | | |

PROGRAM SCOPE

The licensee is authorized to distribute electron tubes containing nickel-63; ionizing radiation measuring instruments containing chlorine-36; sealed sources containing chlorine-36; and byproduct material as identified in licensee's letter dated May 25, 2004, and as specified in Section 30.71, Schedule B, to persons exempt from licensing pursuant to Sections 30.15 and 30.18, 10 CFR Part 30, or equivalent provisions of the regulations of any Agreement State. The license does not authorize possession or use of licensed material, only to distribute products authorized by the licensee's State of Ohio radioactive material license.

Performance Observations

During the inspection, the licensee's RSO demonstrated/discussed: (1) labels for products; radiation safety instructions for products and transfer of byproduct material to persons exempt pursuant to 10 CFR 30.18 or equivalent agreement state regulations. Distribution of Cl-36 sources are limited to individuals in need of replacement sources in instruments purchased earlier per the provisions of 10 CFR 32.14. Any source transfer under the license must be authorized by the RSO prior to transfer and the RSO maintains a log of each shipment for annual reporting requirements. The licensee has submitted material transfer reports as required in Section 32.16, 10 CFR Part 32.