


UNITED STATES NUCLEAR REGULATORY COMMISSION

REGION IV 1600 EAST LAMAR BLVD ARLINGTON, TEXAS 76011-4511

EMAIL



Name: Organization: Michelle White

DMS Health Technologies

License No. 40-32477-01 Docket No. 030-3640¹ Control No. 576221

E-mail address:

michelle.white@dmshg.com

Phone:

605-366-1293

From:

Jacqueline D. Cook

Date:

April 5, 2012

Subject:

Application dated October 12, 2011 for License Renewal

Pages:

2

Ms. White:

Per your application dated October 12, 2011, the items on the next page are deficiencies which require your response. Please respond to this e-mail by Friday, April 13, 2012. Please note that I will be out of the office Tuesday, April 10-the afternoon of Thursday, April 12, 2012. Our fax number is (817) 200-1263. You may respond by e-mail in pdf format if you'd like. My email address is jackie.Cook@nrc.gov. When responding to this e-mail, please include the license, docket and control numbers located at the top of this page.

Thanking you in advance for your cooperation, assistance, and prompt response in this matter.

/RA/

Jacqueline D. Cook Senior Health Physicist Please note that I reviewed your renewal application utilizing the guidance found in NUREG-1556, Vol. 9, Rev. 2 (http://www.nrc.gov/reading-rm/doc-collections/nuregs/staff/sr1556/v9/r2/).



Please note that it is NRC policy to not recognize an Alternate Radiation Safety Officer (ARSO) on a license; however, the licensee can do so internally at their discretion.

The Radiation Safety Officer (RSO) is responsible for the overall management of the radiation safety program; identifying radiation safety problems, initiating, recommending or providing corrective actions; verifying implementation of corrective actions; ensuring compliance with the Commission's rules and regulations and conditions of the license. An RSO should actively participate in the day-to-day management of the radiation safety program. Although the performance of certain radiation safety tasks may be delegated by the RSO to other individuals (such as an ARSO), the responsibility for the overall effectiveness of the radiation safety program and for compliance with NRC rules and regulations and conditions of the license reside with the RSO.

Therefore, please note that with the issuance of the renewal, Mrs. Mary Hennings-Frank will no longer be listed as an ARSO on the license.

Please acknowledge your understanding of our policy.

- √2. What is Marilin Espino-Maya's title M.D., D.O., etc?
- Please specify the direction of north (N) and the scale used for the 1222 W. Cherry location in Vermillion, South Dakota.
 - Please indicate the scale used for the Watertown, South Dakota and the Madison, South Dakota facility diagrams.
- Please provide the following: A statement that: "We reserve the right to upgrade our survey instruments as necessary as long as they are adequate to measure the type and level of radiation for which they are used."
- Please provide the following statement: "We have developed and will implement and maintain written procedures for area surveys in accordance with 10 CFR 20.1101 that meet the requirements of 10 CFR 20.1501 and 10 CFR 35.70."
 - Please provide the following statement: "We have developed and will implement and maintain procedures for safe use of unsealed byproduct material that meet the requirements of 10 CFR 20.1101 and 10 CFR 20.1301."
- Please provide the following statement: "We have developed and will implement and maintain written procedures for safe response to spills of licensed material in accordance with 10 CFR 20.1101."