



Note: C01 is Source 49; C02 is Source 50.

Progress Energy Carolinas
**Shearon Harris Nuclear Power Plant
 Units 2 and 3**
Part 2, Final Safety Analysis Report
 New Hill, North Carolina

Mean Hazard Curves for the
 Rondout Associates Team Sources
FIGURE 2.5.2-225