

Part 21 (PAR)

Event # 47895

<b>Rep Org:</b> ENERGY SOLUTIONS	<b>Notification Date / Time:</b> 05/03/2012 11:02 (EDT)
<b>Supplier:</b> ENERGY SOLUTIONS	<b>Event Date / Time:</b> 05/03/2012 (MDT)
	<b>Last Modification:</b> 05/03/2012
<b>Region:</b> 4	<b>Docket #:</b>
<b>City:</b> SALT LAKE CITY	<b>Agreement State:</b> Yes
<b>County:</b>	<b>License #:</b>
<b>State:</b> UT	
<b>NRC Notified by:</b> DAN SHRUM	<b>Notifications:</b> GREG WERNER R4DO
<b>HQ Ops Officer:</b> PETE SNYDER	RICHARD CONTE R1DO
<b>Emergency Class:</b> NON EMERGENCY	DEBORAH SEYMOUR R2DO
<b>10 CFR Section:</b>	MARK RING R3DO
21.21(d)(3)(i) DEFECTS AND NONCOMPLIANCE	PART 21 REACTOR GRP EMAIL
	PART 21 MATERIALS GR EMAIL

SHIPPING CASKS TAKEN OUR OF SERVICE FOR ACCIDENT SCENARIO NOT PREVIOUSLY ANALYZED

"This serves as notification of a regulatory compliance issue with the 10-160B Type B Cask (Certificate of Compliance #9204) and the 8-120B Type B Cask (Certificate of Compliance #9168). This notification is being made in accordance with 10 CFR Part 21.21(d)(3)(i). These casks have been administratively placed out of service as Type B Packages until a complete determination can be made by Energy Solutions and the Nuclear Regulatory Commission (NRC).

"As part of the relicensing of new 8-120B Casks, Energy Solutions identified a hypothetical accident scenario required by 10 CFR 71 which was not previously analyzed as part of the original or ongoing licensing activities. This analysis confirmed that the current cask design does not comply with the Type B package requirement for this specific accident scenario. The 10-160B has a similar design. As such, the casks have been placed out of service. Energy Solutions initiated Condition Report ENG-CR12-018 to track this issue.

"In accordance with 10 CFR Part 21.21(d)(4), Energy Solutions will provide written notification to the NRC within 30 days with additional information including corrective actions."

\*\*\*\*\*

IE20  
NMSS

ATTN:

FROM: Karen Kirkwood

DATE: May 03, 2012

SUBJECT: Required Notification to NRC

JOB: 9130

ATTACH: "Required Notification to NRC.pdf"

This Fax Originated From a Biscom 'Faxcom'.

MEMO:.....

This is being sent on behalf of Dan Shrum, EnergySolutions.

Karen Kirkwood  
Administrative Assistant of Regulatory Compliance  
EnergySolutions  
423 West 300 South, Suite 200  
Salt Lake City, UT 84101  
Phone: 801-649-2146  
Fax: 801-413-5646



*Fax Cover Sheet*

**Date: May 3, 2012**

**To: Operations Center**

**From: Dan Shrum**

**Company: Nuclear Regulatory Commission**

**Phone: (301) 816-5100**

**Phone: 801-649-2000**

**Fax: (301) 816-5151**

**Fax: 801-416-5646**

**Re: Required Notification**

---

**Number of pages including cover sheet: 2**

---

**Message: See attached notification**

This facsimile transmission (and/or the documents accompanying it) is intended only for the use of the individuals or entities to whom it is addressed. This transmission contains information from EnergySolutions which may be privileged, confidential or exempt from disclosure under applicable law. If the reader of this transmission is not the intended recipient, you are hereby notified that any dissemination, distribution, copying or the taking of any action in reliance on the contents of this transmission is strictly prohibited. If you have received this transmission in error, please notify us immediately at our telephone number listed below. We will be happy to arrange for the return of this transmission to our offices at no cost to you.

423 West 300 South, Suite 200 • Salt Lake City, Utah 84101 • 801.649.2000 • Fax: 801.321.0453

[www.energysolutions.com](http://www.energysolutions.com)



**Date:** May 3, 2012

**Notification To:** NRC, Operations Center (301) 816-5100

**Notification From:** Dan Shrum, EnergySolutions Senior Vice President,  
Regulatory Affairs

*See McClellan  
for Dan Shrum  
5/3/12*

**Notification:** This serves as notification of a regulatory compliance issue with the 10-160B Type B Cask (Certificate of Compliance #9204) and the 8-120B Type B Cask (Certificate of Compliance #9168). This notification is being made in accordance with 10 CFR Part 21.21(d)(3)(i). These casks have been administratively placed out of service as Type B Packages until a complete determination can be made by EnergySolutions and the Nuclear Regulatory Commission (NRC).

As part of the relicensing of new 8-120B Casks, EnergySolutions identified a hypothetical accident scenario required by 10 CFR 71 which was not previously analyzed as part of the original or ongoing licensing activities. This analysis confirmed that the current cask design does not comply with the Type B package requirement for this specific accident scenario. The 10-160B has a similar design. As such, the casks have been placed out of service. EnergySolutions initiated Condition Report ENG-CR12-018 to track this issue.

In accordance with 10 CFR Part 21.21(d)(4), EnergySolutions will provide written notification to the NRC within 30 days with additional information including corrective actions.