

Docket File Information
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: PerkinElmer Life Sciences 2200 Warrenville Rd., Downers Grove, IL REPORT NUMBER(S) 12-001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S) 03013133	4. LICENSE NUMBER(S) 12-04933-06E	5. DATE(S) OF INSPECTION 5/14/12
-------------------------------------	--	---

6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 02.06-02.07
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03253	2. PRIORITY 5	3. LICENSEE CONTACT Rick Haines, RSO	4. TELEPHONE NUMBER (630) 322-5202
---------------------------------	----------------------	---	---

Main Office Inspection Next Inspection Date: 5/12/2017

Field Office Inspection

Temporary Job Site Inspection

PROGRAM SCOPE

The licensee distributed instrument calibration sources and standards to persons exempt from licensing. The sources and standards contained carbon-14, hydrogen-3, iodine-125, iodine-129, chromium-51, cesium-137, and cobalt-57. Most products contained less than 1 microcurie.

Performance Observations

The inspectors observed: (1) licensee annual transfer reports that were sent to the NRC since the last inspection per 10 CFR 32.20(d)(1); (2) records of transfer of material that identified the transferees per 10 CFR 32.20(a); (3) that a proper package containing Part No. 6007601 with 0.536 microcuries was ready for distribution with the enclosed radioactivity certificate, and the vial standards and plates were labeled with the radioactivity; (4) that selected records indicated that distributed material was as per 10 CFR 30.71, Schedule B; (5) that selected records indicated that distributed material was in accordance with the Product List referenced in Condition 13 of the NRC license; and (6) that distribution occurred only from the authorized location.

During the inspection, the RSO informed the inspectors that the licensee planned to cease exempt distribution activities by the end of 2012 because the licensee is moving licensed activities from its Downers Grove, Illinois facility to a facility in Boston, Massachusetts by the end of 2013. The inspectors informed IEMA and FSME of the licensee's plans per the proper communication protocols.