



CAMECO RESOURCES
Corporate Office
2020 Carey Avenue
Suite 600
Cheyenne, WY
82001 USA

Tel: (307) 316-7600
Fax: (307) 635-9949
www.cameco.com

February 16, 2012

U.S. Nuclear Regulatory Commission
Attn: Douglas Mandeville
11545 Rockville Pike
Two White Flint North, Mailstop T8 F5
Rockville, MD 20852-2738

CERTIFIED MAIL # 7005 0390 0003 9500 8302 RETURN RECEIPT REQUESTED

RE: Correction to License Renewal Application Electronic Files and Technical Report List of Appendices (TAC J00635)

Dear Mr. Mandeville:

Power Resources, Inc. d/b/a Cameco Resources (Cameco) submitted the updated License Renewal Application for License No. SUA-1548 on February 1, 2012. The purpose of this letter is to supply two corrections to that submittal including electronic files and the table of contents pages for the Technical Report appendices.

The February 1, 2012 transmittal included CDs containing the electronic files comprising the application. Cameco has discovered that the CD containing the technical report appendices (corresponding to Volume 2 of 3 and Volume 3 of 3 of the hard copy) was missing several appendices. Those missing from the original included:

- Appendix B North Butte Wellfield Modeling Study
- Appendix C Gas Hills Groundwater Modeling
- Appendix E Gas Hills Evaporation Pond Design
- Appendix F Gas Hills Drainage Basin Hydrology
- Appendix G North Butte Road Design
- Appendix H Gas Hills Road Design
 - Dry Creek Road
 - Carol Shop Road
- Appendix I Smith Ranch Analysis of Day, Week, and Year Classification
- Appendix J Purge Storage Reservoir No. 2 Shallow Groundwater Characterization Plan

FSME20

Enclosed, please find a CD containing all of the Technical Report appendices including those that had been missing.

The hard copies of the Technical Report you received had all of the appendices included, however, the table of contents for the list of appendices in Volume 2 of 3 and Volume 3 of 3 did not list all of the appendices that were included. In particular, the list did not include Appendix K, *Radiation Doses from Cameco's North Butte Expansion Area In-Situ Uranium Leaching Operations*, and Appendix L, *Radiation Doses from Cameco's Smith Ranch and Reynolds Ranch Expansion Area In-Situ Uranium Leaching Operations*. Hard copies of the replacement Table of Contents for Technical Report Volume 2 of 3 and Volume 3 of 3 are also included with this letter.

I apologize for any inconvenience this may have caused you or your staff. If you have any questions, please contact me at 307.316.7588 or email Josh_Leftwich@cameco.com.

Sincerely,
CAMECO RESOURCES



Josh Leftwich
Director, SHEQ

Enclosures (2)

- 1) CD containing Technical Report Appendices
- 2) Replacement table of contents pages for Technical Report Volume 2 of 3 and Volume 3 of 3

cc: Document Control Desk, NRC

ec: Cameco-Cheyenne