

November 27, 1996

Docket No. 030-31576

License No. 37-28490-01

Robert J. Follett
Acting Branch Manager
Professional Service Industries, Inc.
1707 South Cameron Street
Suite B
Harrisburg, PA 17104

SUBJECT: INSPECTION NO. 030-31576/96-001

Dear Mr. Follett:

On November 19, 1996, Eric H. Reber of this office conducted a safety inspection at your facility of activities authorized by the above listed NRC license. The inspection was an examination of your licensed activities as they relate to radiation safety and to compliance with the Commission's regulations and the license conditions. The inspection consisted of observations by the inspector, interviews with personnel, and a selective examination of representative records. The findings of the inspection were discussed with you, at the conclusion of the inspection.

Based on the results of this inspection, it appears that your activities were not conducted in full compliance with NRC requirements. A Notice of Violation is enclosed and categorizes the violation by severity level in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (Enforcement Policy), NUREG 1600. You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

Item A in the Notice of Violation enclosed with this letter was identified during a previous inspection of your licensed activities and documented in a Notice of Violation enclosed with our letter dated September 18, 1991. From this inspection, it appears that your corrective actions were not effective since this item has recurred. Recurrent and uncorrected violations are given additional weight in the consideration and selection of appropriate enforcement action. Therefore, in your response to this letter, you should give particular attention to those actions taken or planned to ensure that identified items of noncompliance will be completely corrected and will not recur.

RETURN ORIGINAL TO
REGION I

OFFICIAL RECORD COPY

9612060354 961127
PDR ADOCK 03031576
PDR

1207

11/26/96

R. Follett
Professional Service Industries, Inc.

-2-

Please use the enclosed self-addressed green envelope when you respond to this letter to assist us in the timely processing of your response. In accordance with Section 2.790 of NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and your reply will be placed in the Public Document Room (PDR). To the extent possible, your response should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. However, if you find it necessary to include such information, you should clearly indicate the specific information that you desire not to be placed in the PDR, and provide the legal basis to support your request for withholding the information from the public. The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:

Jenny M. Johansen, Chief
Nuclear Materials Safety Branch 3
Division of Nuclear Materials Safety

Docket No.: 030-31576
License No.: 37-28490-01

Enclosure:
Notice of Violation

cc w/enclosure:
Commonwealth of Pennsylvania

R. Follett
Professional Service Industries, Inc.

-3-

Distribution: w/encl

PUBLIC

Nuclear Safety Information Center (NSIC)

Region I Docket Room (w/concurrences)

D. J. Holody, RI

DOCUMENT NAME: R:\WPS\MLDL\13728490.G1

To receive a copy of this document, indicate in the box: "C" = Copy w/o attach/encl "E" = Copy w/ attach/encl "N" = No copy

OFFICE	DNMS/RI	N	DNMS/RI				
NAME	Reber/ehr	Johansen					
DATE	11/27/96	11/27/96		11/ /96		11/ /96	

OFFICIAL RECORD COPY

NOTICE OF VIOLATION

Professional Service Industries, Inc.
Harrisburg, PA 17104

Docket No. 030-31576
License No. 37-28490-01

During an NRC inspection conducted on November 19, 1996, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," (Enforcement Policy), NUREG 1600, the violation is listed below:

- A. Attachment 8, "Training for Individuals Working in or Frequenting Restricted Areas", requires that individuals who use or directly supervise the use of licensed material receive four days of on-the-job training.

Contrary to the above, from March 1, 1993 to November 19, 1996, three individuals used licensed materials and did not receive four days of on-the-job training. Specifically, two gauge users stated that they had each had 8 hours of on-the-job training, and a third gauge user stated he had two to three days of on-the-job training.

This is a Severity Level IV violation (Supplement VII).

Pursuant to the provisions of 10 CFR 2.201, Professional Service Industries, Inc. is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region I, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation, or, if contested, the basis for disputing the violation, (2) the corrective steps that have been taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Your response may reference or include previous docketed correspondence, if the correspondence adequately addresses the required response. If an adequate reply is not received within the time specified in this Notice, an order or a Demand for Information may be issued as to why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

Because your response will be placed in the NRC Public Document Room (PDR), to the extent possible, it should not include any personal privacy, proprietary, or safeguards information so that it can be placed in the PDR without redaction. However, if you find it necessary to include such information, you should clearly indicate the specific information that you desire not to be placed in the PDR, and provide the legal basis to support your request for withholding the information from the public.

RETURN ORIGINAL TO
REGION I

OFFICIAL RECORD COPY

IE07

9612060355 961127
PDR ADGCK 03031576
PDR