

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: DMS Health Technologies Loc: 109 South Petro Avenue, Sioux Falls, SD 917 North Washington, Madison, SD 525 North Foster Street, Mitchell, SD REPORT NO: 2012-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd Arlington, Texas 76011-4511	
3. DOCKET NUMBER 030-36404	4. LICENSE NUMBER 40-32477-01	5. DATE OF INSPECTION June 7, 2012	

LICENSEE:
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation closed. *2009-001*
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.
- Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):
- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11

License condition 9.D. authorizes, in part, the use of a Technical Operations, Inc. Model 773 calibrator for calibration of licensee's survey meters.

Contrary to the above, on five occasions from April 10, 2008, to March 28, 2012, the licensee used its Technical Operations, Inc. Model 773 calibrator for calibration of a survey meter that was not the licensee's.

As corrective action, the licensee committed not to use its calibrator for calibrations of survey instruments that were not the licensee's.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Michelle White	<i>Michelle White</i>	6/21/12
NRC INSPECTOR	Jason M. Razo	<i>Jason M Razo</i>	June 21, 2012
BRANCH CHIEF	Michael Vasquez	<i>Anty W Vasquez</i>	6/20/12