

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Certified Testing and Consulting Services 3144 Venture Drive, Suite 100 Lincoln, California 5648 Location: NASA/Ames Research Center, Moffett Field, CA REPORT NO: 150-00004/2012-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Boulevard Arlington, Texas 76011-4511	
3. DOCKET NUMBER 150-00004	4. LICENSE NUMBER 10 CFR 150.20	5. DATE OF INSPECTION June 27, 2012	

LICENSEE:
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 150.20(a)(1)(ii) provides in part, that any person who holds a specific license from an Agreement State is granted an NRC general license to conduct the same activity in areas of exclusive Federal jurisdiction within Agreement States provided that the provisions of 10 CFR 150.20(b) have been met.




10 CFR 34.89(b)(2) requires that at each temporary job-site, the licensee shall maintain a copy of 10 CFR parts 19, 20, and 34 of NRC regulations.

Contrary to the above, at the NASA/Ames Research Center, building N234-A, a temporary job-site, although the licensee provided a copy of 10 CFR part 20, the licensee failed to maintain a copy of 10 CFR parts 19 and 34 of NRC regulations at the temporary job-site.

The licensee committed to obtaining and to maintain a copy of 10 CFR parts 19 and 34 of NRC regulations from this day forward at any and every temporary job-site in Federal jurisdiction authorized under the provisions of 10 CFR 150.20(b).

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Tony Woods, ARSO		07/02/2012
NRC INSPECTOR	R. Rick Muñoz		07/02/2012
BRANCH CHIEF	G. Michael Vasquez		7/5/12

Non-Public
 Sensitive – Security-Related
 Public
 Non-Sensitive

Munoz, Rick

From: Munoz, Rick
Sent: Monday, July 02, 2012 3:53 PM
To: twoods@ctcservicesinc.com
Cc: Munoz, Rick
Subject: Certified Testing and Consulting Services (Inspection Report - NASA/Ames Research Center (temporary job site))
Attachments: SCAN5620_000.pdf

Mr. Woods,

As per our conversation this afternoon, I have attached a pdf file of an NRC Form 591M which documents one (1) violation identified by the NRC during the inspection at a temporary job site at NASA/Ames Research Center at Moffett Field, CA, which was conducted on June 27, 2012. Please review the Notice, and if you agree with the statements and your corrective actions, please sign and date the 591M form and either return it via electronic mail (pdf) or fax at your earliest convenience. There will be no further response required from you as long as you adhere to your commitments. If you have any questions about the inspection or the 591 please call me at the telephone number listed below.

Kindest Regards,

Rick Muñoz
Nuclear Materials Inspector
U.S. Nuclear Regulatory Commission, Region-IV
1600 East Lamar Boulevard
Arlington, Texas 76011-4511

Office: (817) 200-1220
Cell: (512) 773-8520
Fax: (817) 200-1188
Email: rick.munoz@nrc.gov



The information contained in this message may be privileged and/or confidential and protected from disclosure. If the reader of this message is not the intended recipient, or an employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please notify the sender immediately by replying to the message and deleting the material from any computer.

Note: Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of the Nuclear Regulatory Commission, Region-IV or the Nuclear Materials Safety Branch-A. All e-mails are subject to monitoring and archival.

Finally, the recipient should check this message and any attachments for the presence of viruses. The Nuclear Regulatory Commission accepts no liability for any damage caused by any virus transmitted by this e-mail.
