

C S L

February 21, 1979

A. B. Davis, Chief  
Fuel Facility and Materials Safety Branch  
Nuclear Regulatory Commission  
799 Roosevelt Road  
Gen Ellyn, Ill 60137

13-16501-01


Gentlemen:

With regard to your letter of February 2, 1979 pursuant to our license No. 13-16501-01 please be advised of the following action which we have taken:

1. Address appearing on license - Condition 10  
A request to amend our license to show our new address has been sent and received by your Dr. John Cooper (see copies of our letter to Dr. Cooper and Mail and Records Section acknowledgement of same).
2. Individual named as supervisor - Condition 12  
Same as above.
3. Test of detector for leakage - Condition 13A  
A leakage test kit has been acquirely used, and returned to Tracor Corp of Austin, Texas for evaluation.
4. Records of past leak tests - Condition 13B  
The person conducting past leak tests has been contacted, but we can not find records of the test which he says were conducted.
5. Receipt record for detector containing Ni-63 - 19 CFR 30.51  
Records have been brought together showing purchase order, freight bill and cancelled check pertaining to above (copies attached).

We hope this will bring us into compliance. Full compliance will be achieved upon receipt of Tracor's evaluation of our recent swab test.

Sincerely,

  
Eugene V. Elder, President  
Chemical Service Laboratory, Inc.

EVE:kw

7906190204

23 1979

A-6